
feedback = stage 6 ⊕ stage 7 ⇔ $x^7 + x^6 + 1$
stage 1
stage 2
stage 3
stage 4
stage 5
stage 6
stage 7
D Q
PRBS7 out
clock f_b