
y [mm]
x [mm]
printing (q_0)
moving (q_1, q_2, q_7)
wipe tower
saved points (x_s, y_s)
mode q
T_n [°C]
s [m]
t [s]