
Provisioning a key: PX4 1.17 unaffected; ArduPilot ch0 signs yet still accepts unsigned input
PX4 1.18.0-rc1 GCS
PX4 1.17.0 GCS
still answers unsigned
ArduPilot 4.7.2 SERIAL1
ArduPilot 4.7.2 SERIAL0 (ch0)
still answers unsigned
0
20
40
60
80
100
signed outbound frames (%)
default
after provisioning