AMP6500 SDK Release Notes			
Software Product Name	:		AMP6500 SDK
Hardware Platforms:			AMP 6500
TMS Version Required:			ATMS Agent v2.11.1 (ATMS Agent Library 1.9.0)
New SDK Version:			v1.2.0
Previous SDK Version: Release Date:			v1.1.0 July 8, 2021
Source Repository Locat	ion:		1019 6, 2021
,,			
Dependencies: (Compor	nent used to con	pile this app)	Component version
	AMPPOS Libs		1.7.0
	Minimum API	Level	22
	NDK		13b
	Cmake Android Studi	_	3.6.4111459 version 3.4.2
	Android Studi	0	Version 5-4.2
AMP OS:			
	Firmware:		1.0.22
Other Application requi	red:		None
Sample application inclu	ıded:		AndroidUnattendedDemo
			DemoAppEMV (AMP POS v02.02.005DEM)
			TMSClientDemoApplication (v1.7.0)
C		an Abia mandan	20
Summary of iten			
ITEM	CATEGORY	STATUS	Notes .
1	1 FIX	RELEASED	Updated AMPPOSLibs to 1.7.0
			- updated SNK500 jar file updated ATMS Agent library to 1.9.0
 	2 FIX	RFIFASED	- updated ATMS Agent Library to 1.9.0 Updated ATMSSampleCode to TMSClientDemoApplication (v1.7.0)
	3 FIX		Opported ATMS Agent Lib Release Notes to v1.9.0 Updated ATMS Agent Lib Release Notes to v1.9.0
	4 FIX		Added ATMS Agent Library Developer Guide v1.4
Summary of iten	ns included	on this version	1: v1.1.0
ITEM	CATEGORY	STATUS	Notes
	1 FIX	RELEASED	
	2 FIX	RELEASED	Updated AMPEMVL2 library to 03.00.012
			Updated AMPPOSLibs to 1.6.0
			- updated SDK6500.jar file
	3 FIX	RELEASED	- updated ATMS Agent Library to 1.8.1
			Updated DemoAppEMV to AMP POS v02.02.005DEM
	4 FIX	DELEASED	- modified CMakeLists.txt to add new AMPEMVL2 and AMPCMPNT versions - modified SDK6500.jar file to match the firmware
	5 FIX		Updated ATMSSampleCode based on ATMS Agent V2.10.1 (ATMS Agent Library 1.8.1)
•	J IIX	KELEASED	Opudated AMMP POS 6 and 8 Series Developer Guide to version 1.9 (PDV-8000-1.9-E)
1	6 FIX	RELEASED	- Updated Section 7.1 to include the correct API function to be used in disabling status bar in COSU mode
Summary of items included on this version: v1.0.4			
ITEM	CATEGORY	STATUS	Release Notes:
TTEIVI	CATEGORI	314103	NEICOSE MUTES. NEICOSE MUTES.
	1 FIX	RELEASED	Fix Contactless Timeout Delay to cater other entry modes
	2 FIX	RELEASED	Updated AMP POS 6 and 8 Series Developer Guide to version 1.8 (PDV-8000-1.8-E)
Summary of iten	ns included	on this version	n: v1.0.3
ITEM	CATEGORY	STATUS	Notes
	1 FIX	RELEASED	Updated SampleClientApp (AMP POS v02.02.003SCAw)
	2 FIX	RELEASED	Updated BaseAppSDK to 01.00.004 (included in SampleClientApp source code)
	3 FIX	RELEASED	Updated AMPCMPNT 01.00.005
	4 FIX	RELEASED	Updated AMPEMVL2 library to 03.00.007
	5 FIX	RELEASED	Updated AMPPOSLIS to 1.5.0
-	6 FIX	RELEASED	Added google() for ATMSSampleCode Updated DemoAppEMV to AMP POS v02.02.003DEM
	7 FIX	RELEASED	- modified CMakeLists.xt to add variable names to SDK folder structure
Summary of iton	nc included	on this version	
Summary of items included on this version: v1.0.2 ITEM CATEGORY STATUS Notes			
ITEM			
	NEW	RELEASED RELEASED	Added SampleClientApp (AMP POS v02.02.001SAU) Added AMPCMPNT v1.0.0
	NEW	RELEASED	Added ATMS Agent Library v1.4.0
	NEW	RELEASED	Added ATMS Sample Code
	NEW	RELEASED	Added ATMS Release notes
	FIX	RELEASED	Updated AMPEMVL2 library to 3.0.1
<u> </u>	FIX	RELEASED	Updated AMPPOSLibs to 1.2.0
ļ	FIX	RELEASED	Updated DemoAppEMV to AMP POS v02.02.002DEM Added DNV 2001.1 1 E AMD Andreid Break on Interesting ANI Developer Guido pdf
 	NEW	RELEASED	Added PDV-8001-1.1-E AMP Android BaseApp Integration API Developer Guide.pdf Added PDV-8002-1.0-E AMP Android BaseApp Outbound Integration Developer Guide.pdf
1	NEW	RELEASED RELEASED	Added PDV-5005-2.1-E AMP Android Baseapp Outdound Integration Developer Guide.pdf Added PDV-5005-2.1-E AMP EMV Level 2 Developer Guide.pdf
	NEW	RELEASED	Added PDV-8000-1.2-E AWIF LIW LEVEL E Developer Guide.pdf Added PDV-8000-1.2-E AWIF LIW LEVEL E Developer Guide.pdf
Summary of iten			
ITEM	CATEGORY	STATUS	Notes
	FIX	RELEASED	NOTES Updated AMPEMVL2 Library to 3.0.0
Summary of iten			
	CATEGORY		
ITEM	FIX	RELEASED	Notes Initial release for AMP6500Series SDK
	FIA	RELEASED	
NOTES: The AMP6500	SDK package is d	istributed as a .zin file	. When extracting the package, browse for the AMP8Series SDK package file and extract to the target directory "C:\". The Destination path
			ld be modified to "C:\" (shown below):
The Commands Tools (avoides of Services of			
		Intraction path and options neral Advanced	
1	N Od P	estination path (will be created if does n	Of exist) Chiplay
Add Extract L OS (C)	t To Test View	21	Wen falder
Name	^	Update mode Extract and replace files	□ □ 0.5 (C)
SharedDownlo	oed se Information	Extract and update files Fresh existing files only	iii AMP3 > 7-99rinSDK iii Bedso Zig
TMRescueDisk		Overwrite mode	## skapport ## httpl
Windows Windows old		Asik before overwrite Overwrite without prompt	Perfuce Billion
MAMP2SeriesSE		Skip existing files Rename automatically	Program Files (vills) ii Program Cital ii Swert Chamilad
☐ .md		Miscellaneous	Serve Constanted Serve Constanted United Ser
800TNXT		Extract archives to subfolders Keep broken files	iii — Generalia iii — Generalia iii — Wendown old
Finish.log		Keep broken files Display files in Explorer	III Wedown add
N hiberfl.svs			Series SDK package to be extracted to the correct directory "C:\AMP6500SDK\AMP6500SDKvX.X.X\"
p pose of tins exti	procedul	AITIFO	