
Not sure if Mandatory But harmless Jumpers (most right of each group)

WavePro Related Jumpers Needed only for WP modes testing.

Mandatory Jumpers JP5 , JP6



Switches configuration
(not sure which is critical, but this works)

resistor R111 needs to be professionally removed

Mandatory Jumpers JP44 , JP46

Patch weak resistor between GND and CS of MMSPI header To be professionally added.