



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

72 Keir Close Leamington Spa
Warwickshire CV32 5WE

Certificate No: 72 Keir Close Leamington
Spa Warwickshire CV32
5WE

Engineers Details

Trading Title Coventry Gas Ltd

Address 47 Alspath Road
Meriden

Post Code: CV7 7LU

Gas Safe No: 526645

Telephone No: 07961768920

Installation Details

Installation Address 72 Keir Close
72 Keir Close
Leamington Spa
Warwickshire

Post Code: CV32 5WE

Telephone No: 07465665166

Client Details

Client Address Reeds Rains
35 Regent Grove
Leamington Spa

Post Code: CV32 4NY

Telephone No: 01926311431

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen	Hob	Beiling	Unknown	NA	NA	FL	YES	NA	YES	20 mb	NA	YES	NA	N/A	NO	YES
2	Lounge	Fire	Magiglo	Duo0010637	NA	NA	OF	YES	NA	YES	6.39 kw	YES	YES	YES	PASS	NO	NO
3	Airing Cupboard	Central Heating Boiler	Vaillant	Ecotec Plus 831	9.4	47	RS	YES	0.0005	YES	29.30 kw	YES	YES	YES	N/A	NO	YES
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1	burner on gas hob doesn't ignite with spark generator	advised landlord	NO
2	gas pipe exits through meter in incorrect location	advised landlord	YES
3	meter not sealed through rear exit	advised landlord	YES
4	equipotential bonding not before the first tee	advised landlord	NO
5	gas fire coals not set correctly and broken	advised landlord	YES

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

NO

Number of Appliances Tested:

3

Equipotential Bonding:

NO

NEXT INSPECTION DUE ON OR BEFORE:

Sat-21-Oct-2023

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Fri-21-Oct-2022

Report Received By:

Name:

Signed:

Date: Fri-21-Oct-2022

Gas ID Number: 4464997