## CONVERSION FACTORS FOR THERMAL CONDUCTIVITY UNITS

MULTIPLY											
↓ by appropriate  factor to		Day in	D411 h-1	Day in	aa1 a=1	aa1 a=1	Iron b-1				
factor to OBTAIN—	Btu <sub>IT</sub> $h^{-1}$ $ft^{-1} \circ F^{-1}$	Btu <sub>IT</sub> in. h <sup>-1</sup> ft <sup>-2</sup> °F <sup>-1</sup>	Btu <sub>th</sub> h <sup>-1</sup> ft <sup>-1</sup> °F <sup>-1</sup>	Btu <sub>th</sub> in. h <sup>-1</sup> ft <sup>-2</sup> °F <sup>-1</sup>	cal <sub>IT</sub> s <sup>-1</sup> cm <sup>-1</sup> °C <sup>-1</sup>	cal <sub>th</sub> s <sup>-1</sup> cm <sup>-1</sup> °C <sup>-1</sup>	kcal <sub>th</sub> h <sup>-1</sup> m <sup>-1</sup> °C <sup>-1</sup>	J s-1 cm-1 K-1	W cm-1 K-1	W m <sup>-1</sup> K <sup>-1</sup>	mW cm-1 K-1
OBTAIN-	→ π L.	п. п. г. г.	п. г.	п. п. г. г.	cm · · · C ·	cm · · · C ·	m··C·	Js. cm.K.	w cm·K·	w m·K·	mw cm·K·
Btu <sub>IT</sub> h <sup>-1</sup> ft <sup>-1</sup> °F <sup>-1</sup>	1	12	1.00067	12.0080	$4.13379 \times 10^{-3}$	$4.13656 \times 10^{-3}$	1.48916	$1.73073 \times 10^{-2}$	$1.73073 \times 10^{-2}$	1.73073	17.3073
Btu <sub>IT</sub> in. h <sup>-1</sup> ft <sup>-2</sup> °F <sup>-1</sup>	$8.33333 \times 10^{-2}$	1	$8.33891 \times 10^{-2}$	1.00067	$3.44482 \times 10^{-4}$	$3.44713 \times 10^{-4}$	0.124097	$1.44228 \times 10^{-3}$	$1.44228 \times 10^{-3}$	0.144228	1.44228
Btu <sub>th</sub> h-1 ft-1 °F-1	0.999331	11.9920	1	12	$4.13102 \times 10^{-3}$	$4.13379 \times 10^{-3}$	1.48816	$1.72958 \times 10^{-2}$	$1.72958 \times 10^{-2}$	1.72958	17.2958
Btuth in. h-1 ft-2 °F-1	$8.32776 \times 10^{-2}$	0.999331	$8.33333 \times 10^{-2}$	1	$3.44252 \times 10^{-4}$	$3.44482 \times 10^{-4}$	0.124014	$1.44131 \times 10^{-3}$	$1.44131 \times 10^{-3}$	0.144131	1.44131
cal <sub>IT</sub> s <sup>-1</sup> cm <sup>-1</sup> °C <sup>-1</sup>	$2.41909 \times 10^{2}$	$2.90291 \times 10^{3}$	$2.42071 \times 10^{2}$	$2.90485 \times 10^{3}$	1	1.00067	$3.60241 \times 10^{2}$	4.1868	4.1868	$4.1868 \times 10^{2}$	$4.1868 \times 10^{3}$
cal <sub>th</sub> s <sup>-1</sup> cm <sup>-1</sup> °C <sup>-1</sup>	$2.41747 \times 10^{2}$	$2.90096 \times 10^{3}$	$2.41909 \times 10^{2}$	$2.90291 \times 10^{3}$	0.999331	1	$3.6 \times 10^{2}$	4.184	4.184	$4.184 \times 10^{2}$	$4.184 \times 10^{3}$
kcal <sub>th</sub> h <sup>-1</sup> m <sup>-1</sup> °C <sup>-1</sup>	0.671520	8.05824	0.671969	8.06363	$2.77592 \times 10^{-3}$	$2.77778 \times 10^{-3}$	1	$1.16222 \times 10^{-2}$	$1.16222 \times 10^{-2}$	1.16222	11.6222
J s-1 cm-1 K-1	57.7789	$6.93347 \times 10^{2}$	57.8176	$6.93811 \times 10^{2}$	0.238846	0.239006	86.0421	1	1	$1 \times 10^{2}$	$1 \times 10^{3}$
W cm <sup>-1</sup> K <sup>-1</sup>	57.7789	$6.93347 \times 10^{2}$	57.8176	$6.93811 \times 10^{2}$	0.238846	0.239006	86.0421	1	1	$1 \times 10^{2}$	$1 \times 10^{3}$
W m <sup>-1</sup> K <sup>-1</sup>	0.577789	6.93347	0.578176	6.93811	$2.38846 \times 10^{-3}$	$2.39006 \times 10^{-3}$	0.860421	$1 \times 10^{-2}$	$1 \times 10^{-2}$	1	10
mW cm-1 K-1	$5.77789 \times 10^{-2}$	0.693347	$5.78176 \times 10^{-2}$	0.693811	$2.38846 \times 10^{-4}$	$2.39006 \times 10^{-4}$	$8.60421 \times 10^{-2}$	$1 \times 10^{-3}$	$1 \times 10^{-3}$	0.1	1