Release Notes

CompactLogix SERCOS interface Module Revision 15

Catalog Number 1768-M04SE

About This Publication

Use these release notes for firmware revision 15.37.

Module	Cat. No.
CompactLogix SERCOS Interface	1768-M04SE

Compatible Revisions

To use firmware revision 15.37 of the 1768-M04SE module, update your system to the following revisions.

Update	To Revision
RSLinx software	2.50 or later
RSLogix 5000 software	15
1768-L43 CompactLogix5343 controller	15

Corrected Anomaly in Firmware Revision 15.37

Firmware Revision 15.37 corrects the SERCON816 ASIC chip anomaly.

A SERCOS interface module ring drop and service channel issue was identified as a result of an anomaly occurring in the SERCON816 ASIC chip.

Additional Resources

You can view or download publications at http://literature.rockwellautomation.com. To order paper copies of technical documentation, contact your local Rockwell Automation distributor or sales representative.

Allen-Bradley, CompactLogix, RSLinx, and RSLogix 5000 are trademarks of Rockwell Automation, Inc.

Trademarks not belonging to Rockwell Automation are property of their respective companies.