



Work Order Draft

Customer

MATSON NAVIGATION COMPANY

Asset # Matson-002

Serial # SHB36511

Operator

Customer PO TO FOLLOW

Actual Location PORT AUTHORITY
OF GUAM

Equipment TAYLOR TXCL975

Plate #

Requested By CHRIS MATSON

Jobsite MATSON

SKU	PRODUCT NAME / DESCRIPTION	UOM	QTY / HOURS	RATE	AMOUNT
770-1730	TAPE, ELECTRIC	Each	1	\$7.57	\$7.57
CRCC05089	BRAKE CLEANER	Each	4	\$6.60	\$26.40
	07/27/2026 - Taylor TXCL975 - Mechanic 1	Hour	4	\$200.00	\$800.00
	07/27/2026 - Taylor TXCL975 - Mechanic 2	Hour	3	\$200.00	\$600.00
WORK DONE - 07/27/2026 Initial inspection completed. Hydraulic leak isolated near the lift cylinder.					
	07/28/2026 - Taylor TXCL975 - Mechanic 3	Hour	3	\$200.00	\$600.00
	07/31/2026 - Taylor TXCL975 - Mechanic 1	Hour	2	\$200.00	\$400.00
WORK DONE - 07/31/2026 Installed replacement hose and fittings. Pressure-tested the system and confirmed normal operation.					
	08/11/2026 - Taylor TXCL975 - Mechanic 1	Hour	1	\$200.00	\$200.00
	08/11/2026 - Taylor TXCL975 - Mechanic 2	Hour	2	\$200.00	\$400.00
WORK DONE - 08/11/2026 Final operational inspection completed. Unit released for service.					

Current Draft Total \$3,033.97

Mechanic Work Summary

1. 07/27/2026 - Taylor TXCL975 - Mechanic 1: 4.00 hours - Mechanic 2: 3.00 hours - 7.00 total hours
2. 07/28/2026 - Taylor TXCL975 - Mechanic 3: 3.00 hours - 3.00 total hours
3. 07/31/2026 - Taylor TXCL975 - Mechanic 1: 2.00 hours - 2.00 total hours
4. 08/11/2026 - Taylor TXCL975 - Mechanic 1: 1.00 hours - Mechanic 2: 2.00 hours - 3.00 total hours

Work Description

Inspect and repair the reported equipment fault.
Confirm safe operation before returning the unit to service.

Customer acceptance

NAME / SIGNATURE

Received / Approved by LMS Imports

NAME / SIGNATURE