Cost Segregation Study

Harbor House (sample)

1200 Harbor Boulevard, Ventura, California

Prepared for	Harbor House Holdings LLC (sample)
Prepared by	Alder & Pine Engineering (sample)
Engineer	Alex Morgan, PE
Property use	Nonresidential (transient lodging), 39-year building
Placed in service	November 1, 2026
Revision	2

SAMPLE — synthetic data for the Basis interface. Not a professional study; not for tax use.

Summary by recovery class

Purchase price	$1,240,000.00
Capitalized acquisition costs	$6,000.00
Land (appraisal site value)	$280,000.00
Building basis	$960,000.00
Total depreciable basis	**$966,000.00**

Recovery class	Rows	Replacement cost	Allocated	Share
5-year	9	$47,518.80	$34,874.67	3.6 %
7-year	1	$655.25	$480.90	0.0 %
15-year	4	$140,531.87	$103,138.21	10.7 %
39-year	22	$1,127,525.77	$827,506.22	85.7 %
Total			**$966,000.00**	**100.0 %**

Every priced row is depreciated at the age-life rate 0.266667 and scaled by one factor, 1.000791371, so the rows sum to the total depreciable basis. Building replacement cost new: $1,116,945.97 from the sample square-foot model; reconciliation: reconciled.

SAMPLE — synthetic data for the Basis interface. Not a professional study; not for tax use.

Asset schedule

Asset	Room	Class	Allocated
Kitchen cabinets	Kitchen	5-year	$12,182.78
Countertops	Kitchen	5-year	$3,026.42
Kitchen sink and faucet	Kitchen	39-year	$1,228.97
Range	Kitchen	5-year	$6,839.46
Range hood	Kitchen	5-year	$2,244.19
Decorative light fixtures	Kitchen	5-year	$1,367.90
Furniture (bar stools)	Kitchen	7-year	Unpriced
Hardwood flooring	Kitchen	39-year	$5,530.97
Built-in shelving	Kitchen	5-year	$1,977.03
Windows	Kitchen	39-year	$1,549.57
Exterior glass doors	Kitchen	39-year	$5,129.60
HVAC diffusers	Kitchen	39-year	$277.85
Fireplace (linear, gas)	Living room	39-year	$5,557.06
Built-in shelving	Living room	5-year	$3,954.06
Decorative wood wall panel	Living room	5-year	$2,598.88
Decorative light fixtures	Living room	5-year	$683.95
HVAC diffusers	Living room	39-year	$555.71
Exterior glass doors	Living room	39-year	$5,129.60
Windows	Living room	39-year	$1,549.57
Furniture (sofa)	Living room	7-year	Unpriced
Hardwood flooring	Living room	39-year	$7,483.08
Windows	Primary bedroom	39-year	$3,099.12
Exterior glass doors	Primary bedroom	39-year	$5,129.60
Recessed lighting	Primary bedroom	39-year	$1,025.92
HVAC diffusers	Primary bedroom	39-year	$277.85
Smoke detector	Primary bedroom	39-year	$90.83
Hardwood flooring	Primary bedroom	39-year	$4,554.91
Swimming pool	Exterior & pool	15-year	$72,669.28
Patio paving	Exterior & pool	15-year	$19,987.40
Landscaping (artificial turf)	Exterior & pool	15-year	$9,135.02

SAMPLE — synthetic data for the Basis interface. Not a professional study; not for tax use.

Asset schedule (continued)

Asset	Room	Class	Allocated
Exterior site lighting	Exterior & pool	15-year	$1,346.51
Security camera	Exterior & pool	7-year	$480.90
Fencing	Exterior & pool	15-year	Unpriced
Detached pavilion	Exterior & pool	39-year	$42,639.34
Building structure: substructure	Building	39-year	$81,974.16
Building structure: shell	Building	39-year	$224,335.41
Building structure: interiors	Building	39-year	$138,223.41
Building structure: services	Building	39-year	$240,413.49
Building structure: equipment & furnishings	Building	39-year	$51,750.20

SAMPLE — synthetic data for the Basis interface. Not a professional study; not for tax use.

Engineer’s certification

I developed the analysis in this report, and the statements of fact in it are true and correct.
I inspected the property on October 20, 2026.
The recovery periods follow Rev. Proc. 87-56 and IRC § 168.
My compensation is not contingent on the results of this study, and I have no present or prospective interest in the property.

Alex Morgan, PE · signed in Basis

SAMPLE — synthetic data for the Basis interface. Not a professional study; not for tax use.