#### Contents

1	Task Analysis	1
2	Requirements 2.1 Sensor Board requirements	<b>2</b>
3	Available solutions	2
4	Selection of devices	3
5	PCB design 5.1 Schematics	3
6	Manufacturing6.1 Collecting source data6.2 Manufacturing of the Printed Circuit Board6.3 Preparation for machine surface mount technology6.4 Finalization of the prototype	8
7	Testing 7.1 Errata	9

We wanted to find a suitable hardware in the beginning of the project, but we ...

# 1 Task Analysis

When we define our complete task in the first step, then we can derive all requirements for our solution. When we know the requirements we can start the full development process. Finally, we can check if our project was successful based on the previously defined requirements.

#### Movement analysis task description

- 1. Measuring of the movement of a subject
- 2. Logging the measured data and sending them to post-processing
- 3. Analysing of the movement and naming the specific categories of movements

The subject is an animal – horse in this paper – or human being or a moving machine. The post-processing can be done real-time during the measuring process, but this is not mandatory.

The analysis is primarily focused to recognizing known movements in the logged data. For example the categories of movement of a horse can be: stand, walk, trot, gallop, ...

## 2 Requirements

The requirements are derived from the section 1.

Measuring of the movement of a subject: The solution should work outdoor. So, we cannot take into account any studio or laboratory based technologies like Motion Capture (Mocap). On the other hand we can replace the passive or active markers by whole sensors and remove the necessary cameras. The sensor based electronics is easier to install and can be used in large and complex areas. Based on this outdoor requirement I will consider only wearable sensor systems.

Logging the measured data and sending them to post-processing: There are no wires acceptable in outdoor use, so we can log the data to internal memory or transmit them via any wireless technology. The wireless systems may be not fully reliable in complex areas with many objects. So, when we want to transmit the data directly it's still better to log them internally for later downloads.

Analysis of the movement and naming the specific categories of movements This is a software requirement, so it's not very important during the hardware design. But this requirement defines what data we need to measure and this is a hardware requirement.

For the movement reconstruction we need primarily data about position and attitude of every sensor. Some methods for movement classification don't need to know the exact location (for example accelerometer based step counter). This task is focused on developing a new analysis of the movement, so we cannot say now what sensors will be needed in the future. We can make a prediction that we need an inertial measurement unit (IMU) or some location sensors. But there are some other sensors that produce interesting data according to the movement analysis, for example a heart rate sensor.

Finally, I would like to add as many interesting sensors as possible, because it will give us more data sources and we are less limited by the data sources. The other advantage is multifunctionality of the hardware. On the other hand these additional sensors should be added into the requirements with low importance. Otherwise the selection of an appropriate hardware (based on the requirements) will be manipulated by number of probably unnecessary sensors.

## 2.1 Sensor Board requirements

Finally, I've chosen a wearable sensors technology. The next requirements are specific to this technology and focused on selection of the devices. Let's call a used wearable device or devices as Sensor Board. The table ?? shows the list of requirements for this Sensor Board.

//todo: table

#### 3 Available solutions

Based on the requirements, the selection is mainly focused to sensors with possible outdoor use such as wearable sensors. The table ?? shows the available solutions I have found.

//todo: tabulka existujicich reseni

Table 1: Sensor Board requirements

Category	Requirement	Importance	Comment

Table 2: My caption

Category	Requirement	Importance	Comment

#### 4 Selection of devices

## 5 PCB design

The PCB design should meet both electrical and mechanical requirements. It's usually easier to design a large board in the first iteration, which is used only in the laboratory for software development and testing. Then the second iteration brings the first practically usable device and probably the third iteration is the first one dedicated for production use.

Here in this process I will merge the first and the second version together. I will create a larger device which is still usable as wearable device. This implies that I can do the software development, laboratory tests and the first outdoor tests with the same board designed during the first iteration. I'm going to decrease the dimensions of the first prototype by splitting the PCB to separate sandwich modules. The testing process should give us advantages and disadvantages of this mechanical solution.

I have used CadSoft EAGLE (Easy Applicable Graphical Layout Editor) [?] during this process. I've finally chosen this editor because it has the availability of the libraries for the devices I wanted to use. I would probably use KiCad [?] if there was the same availability of the libraries.

## 5.1 Schematics and board layout

The schematics and the board layout was created in CadSoft EAGLE [?]. The figures 5.1 and 5.1 shows the exported schematics split into two sheets. The exported PCB layout drawing in scale 1:1 is in figure 5.2 and in scale 2:1 with more details in figure 5.2.

## 5.2 Mechanical layout and connectors

//todo: obrazek SVG

## 6 Manufacturing

//todo: pridat vsude fotky jednotlivych fazi

The manufacturing process of the prototype consists of these steps:

- 1. Collecting source data schematics and board layout (in this paper in Eagle)
- 2. Manufacturing of the Printed Circuit Board (PCB)




Figure 1: Schematics of the Sensor Board sheet 1







Figure 2: Schematics of the Sensor Board sheet 2



Top and Bottom layer



Only Top layer



Only Bottom layer

Figure 3: Sensor Board layout in scale 1:1




Figure 4: Sensor Board layout in detail scale  $2{:}1$ 

- (a) Panelization of the board layout
- (b) Adding calibration markers
- (c) Export gerber files
- (d) Send exported files to manufacturing company
- 3. Preparation for machine surface mount technology (SMT)
  - (a) Export data for template for applying solder paste
  - (b) Export partlist list of all devices with their coordinates
  - (c) Export bill of materials (BOM)
  - (d) Manufacturing of the template for applying solder paste
  - (e) Order all devices according to BOM
  - (f) Sending template for applying solder paste, packages with devices and partlist to the manufacturer
- 4. Finalization of the prototype
  - (a) Hand soldering of some remaining devices like connectors or wires
  - (b) Completing the final prototype from possible parts and packaging
  - (c) Applying power and first testing

#### 6.1 Collecting source data

The source data may be in various formats according to the used tools. I used CadSoft EAGLE [?] during the development, but many other tools are available on the market. It depends on the manufacturer company if they accept the source data in our format. They usually accept the source data, but they usually apply an exporting fee. All PCB editors should be able to export the manufacturing data in standardized formats. (Sometimes it's very hard or impossible to edit the exported data.)

## 6.2 Manufacturing of the Printed Circuit Board

When we have more than one board we should assemble all boards onto one or more panels. If we plan to solder the devices by machine we should add a calibration marks on the final panel. I have followed the instructions from SMTplus company [?].

First, I have panelized the seprated boards and I have added the calibration marks according to the rules of SMTPlus company [?]. Finally, I have exported the gerber files using a CAM job [?] in Eagle. I have followed the design rules for class 3 by Gatema a.s. company [?].

## 6.3 Preparation for machine surface mount technology

We need the PCB, template for soldering paste and all devices in this step. Some PCB manufacturers offer creating the template as well, so this is the way I used. The thickness of the template indicates the volume of the paste on each pad. For my small SMDs I used  $100 \, \mu m$ , but I recommend to discuss the parameters with the manufacturer.

The BOM and partlist export depends on the used design tools. When we connect used devices in the sources directly with their part numbers on selected shops, we can simply export the partlist and then import it on the seller's website. I recommend to buy some spare devices to minimize the risk of their damage.

#### 6.4 Finalization of the prototype

We can discuss the finalization work with the manufacturer, but when we create a prototype, I have to recommend to do this job by ourself. It allows us to perform some tests before packaging and we don't have to spend time and money with preparation of the documentation about how to assemble and package our prototype. Otherwise the different software developers and testers can receive the different parts of the prototype for their next work.

## 7 Testing

The testing process has been split into two parts: the laboratory testing during the software development and the outdoor testing. I have found some errors in the version 1.0 during the laboratory testing. These errors are described in Errata list in section 7.1. I did another tests against the specification of used devices. The results show us what devices should be used in the next version of the hardware and what devices are redundant. The results are shown in the section 7.2. The outdoor tests didn't find any significant errors, but there were found several recommendations for the future versions of the Sensor Board. These recommendations are mentioned in section 7.3.

#### 7.1 Errata

The table 2 shows all errors I have found during software development and laboratory testing of the Sensor Board prototype.

#### 7.2 Device testing

The device testing may select the devices used in the future versions and remove all spare parts from the prototype. The table 3 shows the test results and the table 4 shows the devices that I recommend to use in future versions.

#### 7.3 Recommendations for the next version

Recommendations for the future versions of the Sensor Board based on the outdoor testing:

- Replace software LEDs by one or more RGB LEDs. For example WS2812 RGB LED [?].
- Move the sensor fusion and computations to Atmel SAM D21 [?] processor inside the BMF055 [?] chip. Keep the ESP32 [?] processor only for communication and user computations.
- Decrease board dimensions using 4 layer PCB. The increased cost for 4 layer board may be saved on smaller surface.
- Sometimes it is better to have all SMDs at one side of the board. The manufacturing is cheaper and the space on the second side can be used for example for battery mounting or for connectors.
- Split the board area to an area for sensors, an area for power electronics and an area for computing. The power distribution is easier in this situation and the sensors are less influenced by other electronics.

Table 3: Errata of the Sensor Board

Table 5: Bilata of the School Beard			
Severities			
Low No significant affects			
Spare Only spare devices may not work			
Medium   Some part of the prototype may not			
High	The prototype has to be remade		

High The prototype has to be remade				
Number	Description	Error created	Image	Severity
	-	during		
	Bridge between boards under	3328		
	micro USB connector			
1	What happens:	panelization		Low
	The micro USB connector may			
	be placed with lower accuracy			
	Swapped MISO and MOSI on			
	pins IO19 and IO21 on the			
	ESP-WROOM-32 chip according			
	to ESP32 Arduino standard			
	lo Esi 32 iliadillo sudidala			
2	What happens:	schematics		Medium
	The SPI interface is not working	design		
	in Arduino compatible mode			
	without modification of the			
	Arduino SPI library LED5 connected to IO35 on			
	ESP-WROOM-32 is not working			
	LSI - WITOOM-92 IS NOT WOLKING			
3	What happens:	schematics		Spare
	The pins IO34 – IO39 are input	design		
	only, so they cannot drive a LED Missing pull-up resistors on SD			
	card			
	Cara			
	What happens:			
4	The SDIO interface needs ex-	schematics		Medium
	ternal pull-up resistors to work	design		
	properly. I have added these			
	resistors later by hand.			
	The temperature measurement			
	is placed very close to the main			
	processor			
5	r	board layout		Spare
	What happens:	Source ray out		~ Paro
	The processor heating affects the			
	measured temperature			
	Low capacity capacitor plased on			
	power supply			
	What happens:			3.6.3
6	When we use WiFi some	schematics		Medium
	brownouts can be detected.	design		
	I have added a bigger capacitor			
	later by hand			
	The light sensor is placed on			
	inner sideof the board			

Table 4: Device tests

Device	Test	Result
MPU9250	SPI interface	Warning
	I2C interface	
//todo		

Table 5: Device selection

Decision		Device	Decision	
Selected	recommended for use in future versions	MPU9250	Removed	
Possible	Not necessary, but has use-cases	BMF055	Selected	
Removed	Not recommended or will be spare	//todo	•••	

- Use another driver with more capabilities for USB connection. The USB on board actually supports only UART communication on virtual COM port. The File Transfer protocol for the SD card should be supported, too. (If it is needed we can add full USB host support or USB-C compatibility.)
- Add specialized pads for oscilloscope. The pads are connected to the signal and to the ground, so the oscilloscope measurements are more accurate.

//todo: move to index.tex