




RX50 Seek/Interface PCB Sheet@




RX50 Seely/Interface PCB Sheet 3







RX50 Spindle Motor Speed Control PCB



RX50 R/W PCB Short (1)



RXSO R/WPCB Short 2)



+12V

[m