Display Enable Status = 0

Display Enable Status = 1

① Wait until scan is finished

② Wait until retrace is finished

③ Update CRTC address