

A'

a_{00}	a_{01}	a_{02}	a_{03}
a_{10}	a_{11}	a_{12}	a_{13}
a_{20}	a_{21}	a_{22}	a_{23}
a_{30}	a_{31}	a_{32}	a_{33}

*******B'**

b_{00}
b_{01}
b_{10}
b_{11}

b_{11}	t_4
b_{10}	t_3
b_{01}	t_2
b_{00}	t_1

 t **C'**

$c_{00} = a_{00} \times b_{00} + a_{01} \times b_{01} + a_{10} \times b_{10} + a_{11} \times b_{11}$
$c_{01} = a_{02} \times b_{00} + a_{03} \times b_{01} + a_{12} \times b_{10} + a_{13} \times b_{11}$
$c_{10} = a_{20} \times b_{00} + a_{21} \times b_{01} + a_{30} \times b_{10} + a_{31} \times b_{11}$
$c_{11} = a_{22} \times b_{00} + a_{23} \times b_{01} + a_{32} \times b_{10} + a_{33} \times b_{11}$

			a_{11}	a_{10}	a_{01}	a_{00}
		a_{13}	a_{12}	a_{03}	a_{02}	
	a_{31}	a_{30}	a_{21}	a_{20}		
a_{33}	a_{32}	a_{23}	a_{22}			
t_7	t_6	t_5	t_4	t_3	t_2	t_1

 t 