NB: tab on the MKS board EXP connectors MKS-DLS32 IO Expander Boards FOR/REV/PWM is flipped 180 compared to tab on this board, but pin number order is the same Build-Brighton-CNC v0.9 (12/02/2023)

IO to be patched on the MKS-DLC32: gpio No. Net From To SDA J2.3 EXP2.4 DFU Mode on reset SCL J2.4 EXP2.5 GPIO.4

I2SO.7 has a 500mA OC/24V connector on the MKS GPIO.32 has an 800mA OC/24V screw terminal on the MKS These outputs do not have GND. so cannot be use as switch outputs



