PGT 2096/22 APR/SAW-ADA A/C: TCNBF	Page 1
[OFP]	
**** DISPATCH RELEASE ****	
OFP 21 -22 APR-PREPARED BY:G.KOKTURK STN-TEL:+90 216 56	07261
PC2096/PGT94F TCNBF/320 SELCAL/CHKQ ROUTE: SAWADA1	• • • •
DEP: LTFJ 06 ELEV 293 FT COST INDEX: 13 TTL G/C DIST: 365N ARR: LTAF 05 ELEV 54 FT SPEED: ECON TTL F/P DIST: 417N ALT: LTDA 22 PERF: 5.8% TTL AIR DIST: 368N ERA: MSR 4 AT BAG INIT FL/TEMP: 350/TKOF ALT: AVGE WC: P052	M M M53
EDOW ZFW TOW LAW LTFJ/SAW STD 1745 ETD 43659 MAX 64300 75000 67400 LTAF/ADA STA 1915 ELD PLN 56897 65173 62901 HRS 0130	1910
PAX: 155 CGO: CTOT:	
ROUTING: N0433F350 ASMAP UT341 BAG UW75 SELVI W75 KEMER KEMER1D	
FUEL ENDUR:	
002272 0059 TRIP FUEL 000200 0005 MINCONT 000986 0027 ALT / LTDA / MIN DIV 1877 000891 0030 FINAL RES ADDFU 004349 0201 MIN T/O FUEL 003927 0142 EXTRA TKG / POSS 4499L 000299 0026 TAXI 008575 0343 BLOCK / MTCAP 18992 TOTAL FOB / EXTRA REASON: MEL-CDL ITEM 21-63-03A DESCRIPT (REF.ONLY SEE TECH.LOG FOR LAST STA AIR CONDITIONING/COCKPIT AND CABIN TEMPERATU NTROL/HOT AIR PRESSURE VALVE CHECKED CLOSED AY BE INOPERATIVE IN THE CLOSED POSITION PROTENT: 1) HOT AIR PB-SW IS SET TO OFF, AND 2 AIR PRESSURE REGULATING VALVE IS CHECKED CLOSED ON THE COND SD PAGE. COMPANY REST. "THIS IS NOT A MEL/CDL ITEM. THIS AIRCRAFT I TRICTED BY COMPANY. PLEASE REFER TO OPERATION ULLETIN "PG-UI-KB-00135_4" RESTRICTIONS DUE GH OIL CONSUMPTION."	RE CO M VIDED) HOT OSED S RES NAL B
FOR ORIGIN, DESTINATION, ALTERNATE(S) AND ENROUTE ALTERNATE(S): CFPL CHECKED : ENGLISH LEVEL CERT : MET REP. CHECKED : CAT III CARD : SIG WX CHARTS CHECKED : RECURRENT TRNG CARD : NOTAMS CHECKED : VML/OML SITUATION : PERF. ANALYS CHECKED : (GLASSES IF NEC.) : LICENCE AND DATE : PILOT OML SITUATION : MED LICENCE AND DATE : HEAD SET, FLASH LIGHT, : PASSPORT, LDG CARD (WORK PERM) : SELF BRIEFING FOR CAT (B) AD HAS BEEN PERFORMED : APPROVED BY CPT: GURTUNCA	

PGT 2096/22 A	PR/SAW-ADA	A/C: TCNBF	Page 2

PGT 209	96/22 APR/S	SAW-ADA A	/C: TCNBF	Page 3
		PATCH RELEASE		
OFP 21 -22 AF			STN-TEL:+90 216	5607261
) ROUTE: SAWADA1	• • • • • •
ARR: LTAF 05 ELE	EV 54 FT	SPEED: ECON PERF: 5.8%	TTL G/C DIST: 36 TTL F/P DIST: 41 TTL AIR DIST: 36 INIT FL/TEMP: 35 AVGE WC: P0	7NM 8NM 0/M53
43659 MAX 6430	00 75000	LAW 67400 62901	LTFJ/SAW STD 1745 E LTAF/ADA STA 1915 E HRS 0130	LD 1910
PAX: 155 CGO:	:		CTOT:	
ROUTING: N0433F350) ASMAP UT34	1 BAG UW75 SE	CLVI W75 KEMER KEMER	1D
FUEL ENDUR:				
000200 0005 MI 000986 0027 AI 000891 0030 FI AI 004349 0201 MI	INAL RES DDFU IN T/O FUEL	MIN DIV 1877		
	XTRA TKG / P AXI	OSS 4499L		
008575 0343 BI	LOCK / MTCAP OTAL FOB / E	18992 XTRA REASON:		
MEL-CDL ITEM DESCRIPT (REF.ONLY SEE TECH.LOG FOR LAST STAT) AIR CONDITIONING/COCKPIT AND CABIN TEMPERATURE CO NTROL/HOT AIR PRESSURE VALVE CHECKED CLOSED M AY BE INOPERATIVE IN THE CLOSED POSITION PROVIDED THAT: 1) HOT AIR PB-SW IS SET TO OFF, AND 2) HOT AIR PRESSURE REGULATING VALVE IS CHECKED CLOSED ON THE COND SD PAGE.				
COMPANY REST.	"THIS IS N TRICTED BY	OT A MEL/CDL COMPANY. PLE G-UI-KB-00135	ITEM. THIS AIRCRAFT CASE REFER TO OPERAT 5_4" RESTRICTIONS DU	IONAL B
FOR ORIGIN, DESTIN	NATION, ALTE	RNATE(S) AND	ENROUTE ALTERNATE(S):
CFPL CHECKED MET REP. CHECKED	:	ENGLISH LEVE	L CERT :	
SIG WX CHARTS CHEC	CKED :	RECURRENT TR	RNG CARD :	
SIG WX CHARTS CHEC NOTAMS CHECKED PERF. ANALYS CHECK LICENCE AND DATE MED LICENCE AND DA	:	VML/OML SITU	JATION :	
LICENCE AND DATE	: :	PILOT OML SI	TUATION :	
MED LICENCE AND DA	ATE :	HEAD SET, FI	LASH LIGHT, :	
PASSPORT,LDG CARD SELF BRIEFING FOR	(WORK PERM)		:	
APPROVED BY CPT: GURTUNCA				

PGT 2096/22 APR/SAW-ADA	A/C: TCNBF	Page 4

PGT 2096/22	2 APR/SAW-AD	A A/C: TCNB	F Page 5
OFP 21 -22 APR-PF	REPARED BY:G.KOK	TURK STN-TEI	1:+90 216 5607261
PC2096/PGT94F TCN	IBF/320 SELCAL	/CHKQ ROUTE:	SAWADA1
DEP: LTFJ 06 ELEV 29 ARR: LTAF 05 ELEV 54 ALT: LTDA 22 ERA: TKOF ALT:	l FT SPEED: E PERF: 5.	CON TTL F/I 8% TTL AIF BAG INIT FI	P DIST: 417NM R DIST: 368NM
*** LTFJ 131.750 PGT I *** LTAF 131.450 HANDI			
EDOW ZFW 43659 MAX 64300 PLN 56897	75000 67400	: PIC GURTU	JNCA :
PAX: 155 CGO:		CTOT:	
ROUTING: N0433F350 ASM	MAP UT341 BAG UW	75 SELVI W75 KE	MER KEMER1D
ATIS:			
ATC CLR:			
FUEL ENDUR:			
000891 0030 FINAL ADDFU 004349 0201 MIN T/ 003927 0142 EXTRA 000299 0026 TAXI 008575 0343 BLOCK	TT LTDA / MIN DIV RES 'O FUEL TKG / POSS 4499	L	
CALCULATED CO2 EMISSIC	ONS: 8.1 METRIC	TONS	
TANKERING SECTOR GAIN PC2097 LTAF/ADA 05 ZFW: 58.6 PLNTOR	- LTFJ/SAW 06	ALTN LTBR/YEI	I 25R
WEIGHT CHANGE UP 1.0 WEIGHT CHANGE UP 3.0 WEIGHT CHANGE UP 5.0 FL CHANGE DN FL1 FL CHANGE DN FL2	TRIP F TRIP F TRIP F TRIP F	0023 KGS TIM 0071 KGS TIM 0118 KGS TIM 0001 KGS TIM 00023 KGS TIM	ME P 0000 ME P 0000 ME M 0000 ME P 0001

	PGT 209	96/22 APR	/SAV	V-AI	DA .	A/C: TCNBF	Page 6
ALTN/RWY LTDA/22 LTAJ/28 LTAU/25 LTAI/36R	- 0 INFO 0 INFO 0	IST MORA 124 7900 147 9300 203 14800	COMP M000 P009 M013	/LVL /180 /210 /240	TII 002 003	ME/PNLTY FUEL/PNLTY 27/- 00986/- 30/P0003 01132/P0146 40/P0013 01494/P0508 52/P0026 01906/P0920	F.RES 00891 00880 00874
LTAJ/ DC LTAU/ KE	MER1A KEM	1E CT MILBA W' ER W75 SEL' AZ UW74 MU'	VI A2	85 EI	RCIS	ERCIS1J	
			ONB		. ES	T TOF 1811 TOF . I LDG 1910 LDG . FLIGHT .	
RVSM: AL	T SYS LE	FT:				RIGHT:	
	WAYPOINT MORA	AVTT SPD W/V				R/DST MIN ACC ET COORD R	O/ATO F/FU
• • • • • • • • •	LTFJ/06	03/004					3/0.3
ASMAP2J						345/48 012 0012 N4037.9E03042.7 7.	./
UT341	TOC 84	780 32/099		CLB	M01	297/13 005 0017 N4018.7E03138.7 7.	
UT341	ODRUP 84	102 752 32/098				284/43 002 0019 N4016.0E03155.0 6.	
	BAG 86	106 752 32/091				242/45 005 0024 N4004.2E03248.6 6.	./ 8/1.8
UW75 UW75	BAKIR 82	148 750 32/091				197/04 005 0029 N3926.3E03319.5 6.	./ 6/2.0
0W75	AZBUL 59	153 750 32/091				193/73 000 0029 N3922.9E03321.7 6.	./ 6/2.0
	TOD 127	149 749 32/092				120/31 008 0037 N3820.4E03410.1 6.	./ 3/2.3
	SELVI 127	300 33/046		DSC	M01	089/21 004 0041 N3753.9E03430.0 6.	
W75 KEMER1D	KEMER 136			DSC	M04	068/68 003 0044 N3736.1E03443.5 6.	
KEMEKID	LTAF/05 136	33/005		DSC	M02	000 015 0059 N3658.9E03516.8 6.	
ARR.ATIS	÷		• • • • •				

```
PGT 2096/22 APR/SAW-ADA A/C: TCNBF
                                                            Page 7
                      TERRAIN CLEARANCE CHECK
DD CHECK - TERRAIN CHECK COMPLETED WITH NO LIMITATIONS
FOR TOW UP TO 67.2 TONS AND CRUISE ALTITUDE AT OR ABOVE 12000FT
DP CHECK - TERRAIN CHECK COMPLETED WITH LIMITATION
          REVERT TO ESCAPE PROCEDURE
CONSIDERED OXYGEN PROFILE - TIMES MEASURED FROM DECISION POINT:
AFTER 1 MIN DESCEND FL 390
AFTER 4 MIN DESCEND FL 180
AFTER 10 MIN DESCEND FL 140
AFTER 30 MIN DESCEND FL 100
----- -----
*** DP - BAG PLUS 024 NM ***
DECISION POINT N3943.7 E03305.4
PRIOR TO DECISION POINT - TURN BACK BAG(113.1).LTAC/ESB
AFTER DECISION POINT - TURN RIGHT AND DIVERT TO -
BAKIR.UW75.ARMUD.LTAN/KYA
......WIND INFORMATION......
               TOC
CLIMB
                              BAG
                                              AZBUL
350 316/099 -55 390 315/076 -57 390 315/071 -55 390 315/070 -55
310 319/100 -47 370 316/089 -58 370 316/083 -56 370 317/082 -55
200 328/034 -29 350 316/099 -55 350 318/091 -54 350 318/091 -54
150 339/017 -18 330 317/104 -51 330 319/096 -51 330 320/095 -51
100 347/013 -08 310 319/100 -47 310 321/092 -48 310 321/091 -48
TOD
               DESCENT
390 312/070 -53 390 312/070 -53
370 316/082 -54 350 318/092 -53
350 318/092 -53 310 322/093 -47
330 320/097 -50 200 340/020 -29
310 322/093 -47 100 357/013 -09
```

PGT 2096/22 APR/SAW-ADA A/C: TCNBF Page 8
[ATC Flight Plan]
PGT 2096/22 APR/SAW-ADA A/C: TCNBF Page 8 [ATC Flight Plan]

```
PGT 2096/22 APR/SAW-ADA A/C: TCNBF
                                                               Page 9
[ Airport WX List ]
LTFJ --> LTAF PC2096 / 22Apr2019
LIDO/WEATHER SERVICE DATE: 22Apr2019 TIME: 17:20 UTC
AIRMETs:
 No Wx data available
SIGMETs:
 No Wx data available
Tropical Cyclone SIGMETs:
 No Wx data available
Volcanic Ash SIGMETs:
 No Wx data available
DESTINATION AIRPORT:
LTAF/ADA ADANA
  SA
      221650 34009KT 310V020 CAVOK 17/00 01015 NOSIG=
      221640 2218/2318 VRB02KT CAVOK
             BECMG 2309/2311 21012KT=
DESTINATION ALTERNATE:
LTDA/HTY
        HATAY
      221650 25010KT 9999 FEW040 15/05 Q1015 NOSIG=
      221640 2218/2303 25014KT 9999 FEW040=
LTAJ/GZT GAZIANTEP
      221650 32010KT CAVOK 12/00 Q1013 NOSIG=
  SA
      221640 2218/2318 34007KT CAVOK
  FT
             BECMG 2309/2312 SCT040
             TEMPO 2312/2315 34017KT
             BECMG 2315/2318 CAVOK=
LTAU/ASR
          KAYSERI
  SA
      221650 VRB02KT 9999 BKN035 BKN090 04/M01 Q1020 NOSIG=
      221640 2218/2318 VRB02KT 9999 SCT040 BKN100
             BECMG 2222/2301 CAVOK
             BECMG 2303/2306 SCT040
             BECMG 2306/2309 BKN033
             BECMG 2311/2314 SCT040
             BECMG 2316/2318 CAVOK=
LTAI/AYT ANTALYA INTL
      221650 23003KT CAVOK 17/08 Q1017 NOSIG=
  SA
      221640 2218/2318 34008KT CAVOK
             BECMG 2306/2310 18012KT
             BECMG 2314/2318 VRB02KT=
ENROUTE AIRPORT(S):
LTBO/KCO KOCAELI/CENGIZ TOPEL
      221640 2218/2303 VRB02KT CAVOK=
LTBJ/ADB IZMIR/ADNAN MENDERES INTL
      221640 2218/2318 36013KT CAVOK
             BECMG 2218/2221 VRB02KT
             BECMG 2310/2312 FEW030 BKN110=
LTAZ/NAV KAPADOKYA
      221640 2218/2318 VRB02KT 9999 SCT040 BKN100
             TEMPO 2220/2223 -RASN BKN030 BKN080
             BECMG 2300/2302 CAVOK
             BECMG 2306/2309 SCT040
             BECMG 2315/2318 CAVOK=
LTFH/SZF SAMSUN/CARSAMBA
```

FC 221640 2218/2303 29009KT 9999 SCT030 BKN100 TEMPO 2219/2222 -SHRA BKN028 BKN080=

ESCAPE AIRPORT(S):

LTAC/ESB ANKARA/ESENBOGA INTL

SA 221650 01011KT 9999 SCT040 07/M04 Q1020 NOSIG=

FT 221640 2218/2318 VRB02KT 9999 SCT040

BECMG 2218/2221 CAVOK

BECMG 2304/2306 SCT040=

LTAN/KYA KONYA

SA 221650 07005KT 9999 SCT040 07/M02 Q1020 NOSIG=

FC 221640 2218/2303 35007KT 9999 SCT040

BECMG 2218/2220 CAVOK=

DEPARTURE AIRPORT:

LTFJ/SAW ISTANBUL/SABIHA GOKCEN

SA 221650 04011KT CAVOK 11/M01 Q1023 NOSIG=

FT 221640 2218/2318 03009KT CAVOK=

FT 221040 2212/2312 04009KT 9999 SCT040

BECMG 2212/2215 CAVOK

BECMG 2306/2309 SCT035 BKN200=

AIRPORTLIST ENDED

1A3909/18

SABIHA GOKCEN AERODROME

```
PGT 2096/22 APR/SAW-ADA A/C: TCNBF
                                                                                 Page 12
  AMEND TO READ OBSTACLE CLEARCANCE ALTITUDE (OCA) STRAIGHT-IN
  APPROACH INFO AS 560FT (267FT) INSTEAD OF 506FT (213FT)
  REF AD 2 LTFJ IAC-3 AND LTFJ IAC-7
1A2347/19
  ONE OF THE TWY T RETIL (RAPID EXIT TWY INDICATOR LIGHTS) U/S
1A2195/19
  TWY C,E AND TWY D-BTN TWY C AND TWY E- WILL BE TEMPORARILY CLSD TO
  TFC DUE TO ELECTRICITY WORK AS FOLLOWS DATE AND TIME:
  MON: 2200-2359,0000-0130
  TUE: 2200-2359,0000-0230
  WED: 2200-2359,0000-0230
  THU: 2200-2359,0000-0230
  FRI: 2300-2359,0000-0230
  SAT: 2200-2359,0000-0130
  SUN: 2300-2359,0000-0230
1A2078/19
  GRASS CUTTING ON EDGE OF RWY 06/24 AND ALL TWYS.
  -ADVISE TWR INST-
  ELECTRIC MASTS (CABLE CONNECTED EACH OTHER) ERECTED AND NOT
  LIGHTED
  WITH FOLLOWING PROPERTIES
                                  ELEVATION AT TOP HEIGHT(FT)
  COORDINATES
  405504.77N0291754.58E 673.8 FT 405459.54N0291730 01-
                                                                    279.8 FT
                                                                    273.2 FT
                                     679.2 FT
796.5 FT
849.0 FT
741.2 FT
                                                                    279.8 FT
                                                                    276.5 FT
  405452.26N0291719.33E
  405446.83N0291704.04E
                                                                    279.8 FT
  405443.05N0291652.81E
405438.48N0291640.04E
                                                                    229.6 FT
                                      771.1 FT
                                                                    273.2 FT

      405438.48N0291640.04E
      771.1 FT

      405429.48N0291617.67E
      751.7 FT

      405424.68N0291601.66E
      920.6 FT

      405419.44N0291545.77E
      809.0 FT

      405414.92N0291534.20E
      947.2 FT

      405412.21N0291524.94E
      917.8 FT

      405405.53N0291508.01E
      937.9 FT

      405358.68N0291451.63E
      929.4 FT

      405351.22N0291433.76E
      867.8 FT

      405347.23N0291424.21E
      820.8 FT

      405342.70N0291413.37E
      559.8 FT

                                                                    273.2 FT
                                                                    273.2 FT
                                                                    229.6 FT
                                                                    276.5 FT
                                                                    286.4 FT
                                                                    229.6 FT
                                     929.4 FT
867.8 FT
820.8 FT
                                                                    273.2 FT
                                                                    276.5 FT
                                                                    244.4 FT
                                     559.8 FT
                                                                    230.6 FT
1A1672/19
  ISTANBUL SABIHA GOKCEN AERODROME,
  AS OF 06 APRIL 2019 00:01 UTC AMEND TO READ TRANSITION ALTITUDE AS
  12000FT INSTEAD OF 10000FT.
  REF AIP LTFJ PAGES
1A834/19
  PRESENCE THREE MOBILE CRANES WITH FOLLOWING PSN
  300M-1000M BEYOND THR 24
  400M-500M SOUTH OF CENTERLINE
  HEIGHT FROM APRON SURFACE: 60 M
  OBSTACLE LIGHTING: YES
  PRESENCE FIXED CRANE WITH FOLLOWING PSN:
  COORDINATE: 405353.70N0291924.55E
  HEIGHT FROM APRON SURFACE: 21 M
  OBSTACLE LIGHTING: YES
1A749/19
  1-INDIVIDUAL SCHEDULED FLIGHT PERMIT APPLICATIONS FOR ISTANBUL
  SABIHA GOKCEN AIRPORT SHALL NOT BE MADE.
  2-DUE TO INSUFFICIENT CAPACITY AT ISTANBUL SABIHA GOKCEN AIRPORT,
  THE ADDITIONAL FLIGHT PERMITS EXCEPT THE RIGHTS ESTABLISHED UNDER
```

ISTANBUL SABIHA GOKCEN AIRPORT,

THE BELOW MENTIONED DATA/PROCEDURES PUBLISHED IN AIP TURKEY

- 1: RNAV(GNSS)STANDARD INSTRUMENT ARRIVALS (STAR) FOR RWY 06/24:AD2 LTFJ STAR-1,1A,STAR-2,2A
- 2: RNAV (GNSS) STANDARD INSTRUMENT DEPARTURES (SID) FOR RWY 06/24:AD2 LTFJ SID-3,3A,SID-4,4A,SID-5,5A,SID-6,6A
- 3: CONVENTIONAL STANDARD INSTRUMENT DEPARTURES (SID) FOR RWY 06: GAYEM1W, EKI1W, MOPIN1W, BIG1W
- 4: CONVENTIONAL STANDARD INSTRUMENT DEPARTURES (SID) FOR RWY 24: GAYEM1P, MOPIN1F
- 5: LTFJ AD2.22 RNAV AND RADIO FAILURE PROCEDURES.

REF AIP AD2 LTFJ PAGES

CO2/18

CO2/18 COMPANY NOTAM

PLEASE CONSIDER TO INCREASE TAXI FUEL DUE TO HEAVY GROUND TRAFFIC STANDART FLIGHT PLAN TAXI FUEL DETAILS AS BELOW

DEPARTURE TIME TAXI TIME

00:00-07:59 RWY06 24 MIN. - RWY24 24 MIN. 08:00-15:59 **RWY06** 21 MIN. - **RWY24** 21 MIN. RWY06 26 MIN. - RWY24 26 MIN. 16:00-23:59

DESTINATION AIRPORT

===============

LTAF /ADA

1A2367/19

ADANA AIRPORT:

DURING RWY 05 IS USED FOR BOTH LANDINGS AND DEPARTURES AND SUBJECT TO INFRINGEMENT OF CRITICAL AND SENSITIVE AREAS OF GP, PILOTS OF ACFT ON THE ILS COURSE FOR RWY 05 SHALL BE CAUTIOUS ABOUT THAT MOMENTARY DISTORTIONS OR INTERRUPTIONS MAY BE EXPERIENCED IN GP BROADCAST.

CO81/16

CO81/16 COMPANY NOTAM

```
PGT 2096/22 APR/SAW-ADA A/C: TCNBF
                                                      Page 17
 PARKING AREA NUMBER 9 CHANGED AS 113
 PARKING AREA NUMBER 10 CHANGED AS 114
 PARKING AREA NUMBER 10/A CHANGED AS 114/A
 PARKING AREA NUMBER 10/B CHANGED AS 114/B
1A1096/19
 PARKING AREAS NUMBERS ON APRON 1 CHANGED AS BELOW:
 PARKING AREA NUMBER 11 CHANGED AS 115
 PARKING AREA NUMBER 11/A CHANGED AS 115/A
 PARKING AREA NUMBER 11/B CHANGED AS 115/B
1A1059/19
 PARKING AREAS NUMBERS ON APRON 1 CHANGED AS BELOW:
 PARKING AREA NUMBER 12 CHANGED AS 116
 PARKING AREA NUMBER 12/A CHANGED AS 116/A
 PARKING AREA NUMBER 12/B CHANGED AS 116/B
 PARKING AREA NUMBER 13 CHANGED AS 117
 PARKING AREA NUMBER 13/A CHANGED AS 117/A
 PARKING AREA NUMBER 13/B CHANGED AS 117/B
 PARKING AREA NUMBER 14 CHANGED AS 118
 PARKING AREA NUMBER 15 CHANGED AS 119
 MOBILE TACAN AYT CH102X AVAILABLE PPR BEFORE 2 HRS.
ESCAPE AIRPORT(S)
============
LTAC /ESB ANKARA/ESENBOGA INTL
1A2445/19 VALID: 1904221230 - 1904221800
 RWY 03R/21L CLSD TO TFC.
 -ADVISE TOWER INSTRUCTIONS-
CO57/16 COMPANY NOTAM
 ESB/LTAC A/P CATEGORY B COMPETENCE BRIEFING:
 FOR A/P OPR HRS, HANDLING AND FUEL INFO CHECK EFB.
 A/P ELEV: 3125FT. FIRE: CAT9. ATIS: 123.60. RADAR: AVLBL.
 MAIN RWY03R/21L LENGTH:12310FT/3752M. MSA:ANK VOR NDB MAX 8600FT
 INST APPR: RWY03R ILS DME MINIMA 550M/203FT CATII/III AVLBL.
 INST APPR: RWY21L ILS DME MINIMA 550M/200FT
 VISL APPR: RWY03R HIRL CL HIALS-II SFL TDZ RVR
 VISL APPR: RWY21L HIRL CL HIALS-II SFL TDZ RVR
 CIRCLE-TO-LAND MINIMA: RWY03R 1525FT/2400M
 CIRCLE-TO-LAND MINIMA: RWY21L 1525FT/2400M
LTAN /KYA
        KONYA
AD OPERATING HOURS AS FOLLOWS
 DAILY H24
1D17/19
 JP-4 FUEL NOT AVBL.
ENROUTE AIRPORT(S)
IZMIR/ADNAN MENDERES INTL
LTBJ /ADB
```

PGT 2096/22 APR/SAW-ADA A/C: TCNBF Page 18 1A2339/19 RWY 16R/34L SHALL BE USED ONLY AS TWY. FUEL AVBL WITH FUEL TRUCK. 1D538/19 TACAN MEN CH98X UNRELIABLE BEYOND 40NM. 1D537/19 MEN TACAN CH98X HOURS OF OPS/SERVICE: OPERATIONAL HOURS: 0500-1400 SAT SUN AND HOLIDAYS PPR 2 HOURS. CO30/12 CO30/12 COMPANY NOTAM ADB/LTBJ A/P CATEGORY B COMPETENCE BRIEFING: FOR A/P OPR HRS, HANDLING AND FUEL INFO CHECK EFB. A/P ELEV: 410FT. FIRE:CAT9. ATIS:129.20 RADAR:AVLBL. MAIN RWY16L/34R LENGTH: 10630FT/3240M. MSA: MEN VOR MAX 7000FT INST APPR: RWY16L ILS DME MINIMA 750M/202FT INST APPR: RWY34R ILS DME MINIMA 550M/226FT CATII/AVBL. VISL APPR: RWY16L HIRL CL(15M) HIALS-II SFL REIL TDZ HST-G RVR VISL APPR: RWY34R HIRL CL(15M) HIALS-II SFL REIL TDZ HST-I RVR CIRCLE-TO-LAND MINIMA: RWY16L 1090FT/2400M CIRCLE-TO-LAND MINIMA: RWY34R 1090FT/2400M LTBO /KCO KOCAELI/CENGIZ TOPEL 1A2203/19 RIGHT PAPI RWY 27 U/S. 1D547/19 NORTH PAPI RWY 27 OUT OF SERVICE. 1A1888/19 AD OPERATING HOURS AS FOLLOWS DAILY H24 KAPADOKYA LTAZ /NAV $1 \pm 1904 / 19$ AD OPERATING HOURS AS FOLLOWS DAILY H24 LTFH /SZF SAMSUN/CARSAMBA NIL EXTENDED AREA AROUND DESTINATION LTAA ANKARA FIR _____ 1A2069/19 RECENTLY, GPS SIGNAL OUTAGES HAVE BEEN REPORTED BY THE PILOTS OF THE AIRCRAFT OPERATING WITHIN SOME PARTS OF ANKARA FIR. AIRCRAFT OPERATORS OPERATING WITHIN ANKARA FIR ARE ADVICED TO BE CAUTIOUS ABOUT GPS OUTAGES. 1B686/19

EXERCISE WILL TAKE PLACE.

1ST AREA: 373320N0422730E 372943N0422948E 372524N0421759E

372045N0421310E 372029N0420809E 372743N0420850E

VERTICAL LIMITS: 8000FT AMSL-11000FT AMSL

2ND AREA: CENTERED ON 372125N0421020E WITH RADIUS 1 NM

VERTICAL LIMITS: 6000FT AMSL-8000FT AMSL CONTACT: 0312 462 83 47 AND 0553 307 06 00

F) 6000FT AMSL G) 11000FT AMSL

CO17/18

CO17/18 COMPANY NOTAM

A1771/18

RECENTLY, GPS SIGNAL OUTAGES HAVE BEEN REPORTED BY THE PILOTS OF THEAIRCRAFT OPERATING WITHIN SOME PARTS OF ANKARA FIR.

AIRCRAFT OPERATORS OPERATING WITHIN ANKARA FIR ARE ADVICED TO BE CAUTIOUS ABOUT GPS OUTAGES.

ADKAR ADKAR

1A7728/18

SIGNIFICANT POINT -ADKAR- TEMPORARILY ESTABLISHED WITH THE

FOLLOWING PROPERTY:

COORDINATE: 364733N0351152E

REF NOTAM: A7526/18

LT A7526/18

1A7526/18

AIR DEFENCE ZONE ESTABLISHED WITH THEIR FOLLOWING COORDINATES:

AREA: 365846N0352254E 370023N0352409E 370015N0353134E

365745N0353101E 365527N0352837E 365424N0352528E 365358N0352133E 365846N0352254E.

NOTE:NOTAM OF TRAFFIC FLOW REGULATIONS AND ALTERNATIVE ROUTES WILL BE ISSUED.

F) FL110 G) FL450

LT B0158/19

1B158/19

AIR-GND FIRING WILL TAKE PLACE WI ADANA MILITARY TMA (${\tt H24}$):

AREA: CENTERED ON 362351N0351048E WITH RADIUS 0.6 NM

F) SFC G) 15000FT AMSL

LT B1038/19

1B1038/19

AIR DISPLAY WILL TAKE PLACE.

AREA: CENTERED ON 370533N0361417E WITH RADIUS 5NM .

WI ADANA MILITARY TMA .

VERTICAL LIMITS: SFC-8000FT AMSL DATE AND TIME: APR 19 0745-0820

AIR DISPLAY WILL TAKE PLACE.

AREA: CENTERED ON 370533N0361417E WITH RADIUS 5NM .

WI ADANA MILITARY TMA

VERTICAL LIMITS: SFC-15000FT AMSL

DATE AND TIME : APR 22 24 25 1500-1600

F) SFC G) 15000FT AMSL

EXTENDED AREA AROUND DESTINATION ALTERNATE AIRPORT(S)

TUSYR TUSYR

1A5666/15

NAVIGATIONAL WARNING

ALL AIRCRAFT TO ENTER TURKISH AIRSPACE VIA NISAP, TUSYR OR LESRI ENTRY POINTS, BEFORE 5 MINUTES TO THE SUBJECT POINTS, SHALL CONTACT

TO ANKARA ACC THROUGH 125.950 MHz - 119.425 MHz FOR NISAP AND TUSYR,

132.9 MHZ - 127.925 MHZ FOR LESRI OR EMERGENCY CHANNELS.

ANY AIRCRAFT NOT CONTACT TO ANKARA ACC OVER NISAP, TUSYR OR LESRI ENTRY POINTS SHALL NOT BE PERMITTED TO ENTER TURKISH AIRSPACE.

ALE ALEPPO

1A21/19

VOR/DME ALE/ALEPPO 114.5 MHZ/CH92X U.S.

OSTT DAMASCUS FIR

1A38/19

ALL A/C POUND TO DAM FIR SHOULD CALL DAM ACC ON $121.3 \mathrm{MHZ}$ 5 MIN BEFORE ENTER DAM FIR.

IN CASE OF FAILURE CALL LATAKIA TWR ON FREQ 119.2MHZ OR ALP TWR ON FREQ 119.1MHZ.

1A25/18

SECURITY..UNITED STATES OF AMERICA FLIGHT PROHIBITION AGAINST CERTAIN FLIGHTS IN THE DAMASCUS FLIGHT INFORMATION REGION (FIR) (OSTT) 14 CFR 91.1609 SPECIAL FEDERAL AVIATION REGULATION (SFAR) NO. 114 PROHIBITION AGAINST CERTAIN FLIGHTS IN THE DAMASCUS FLIGHT INFORMATION REGION (FIR) (OSTT) WAS PUBLISHED IN THE FEDERAL REGISTER ON 10 DEC 2018 AND WAS EFFECTIVE IMMEDIATELY.

ADDITIONAL INFORMATION IS PROVIDED AT:

HTTPS://WWW.FAA.GOV/AIR_TRAFFIC/PUBLICATIONS/US_RESTRICTIONS/
******LIDO REMARK******

PUBLISHED BY UNITED STATES OF AMERICA ******END OF LIDO REMARK*****

1A9/18

SECURITY..UNITED STATES OF AMERICA ADVISORY FOR AIRSPACE IMMEDIATELY ADJACENT TO DAMASCUS FLIGHT INFORMATION REGION (OSTT FIR). THOSE PERSONS DESCRIBED IN PARAGRAPH A BELOW ARE ADVISED TO EXERCISE CAUTION WHEN OPERATING IN THE AIRSPACE WITHIN 200 NAUTICAL MILES OF THE DAMASCUS FLIGHT INFORMATION REGION (OSTT FIR) DUE TO HEIGHTENED MILITARY ACTIVITY IN OR AROUND SYRIA. THIS MILITARY ACTIVITY MIGHT INCLUDE GPSINTERFERENCE, COMMUNICATIONSJAMMING, AND POSSIBLE

ERRANT LONG-RANGE SURFACE-TO-AIR MISSILES ORIGINATING FROM SYRIAN TERRITORY, WITHIN THE OSTT FIR, AND STRAYING INTO ADJACENT AIRSPACE, THAT COULD POSE AN INADVERTENT RISK TO U.S. CIVIL AVIATION OPERATING IN THIS REGION. TITLE 14, CODE OF FEDERAL REGULATIONS, SECTION 91.1609, SPECIAL FEDERAL AVIATION REGULATION NO.114 PROHIBITION AGAINST CERTAIN FLIGHTS IN THE DAMASCUS FIR REMAINS IN EFFECT.

A. APPLICABILITY. THIS NOTAM APPLIES TO: ALL U.S. AIR CARRIERS AND COMMERCIAL OPERATORS ALL PERSONS EXERCISING THE PRIVILEGES OF AN AIRMAN CERTIFICATE ISSUED BY THE FAA, EXCEPT SUCH PERSONS OPERATING

U.S.-REGISTERED AIRCRAFT FOR A FOREIGN AIR CARRIER AND ALL OPERATORS OF AIRCRAFT REGISTERED IN THE UNITED STATES, EXCEPT

WHERE THE OPERATOR OF SUCH AIRCRAFT IS A FOREIGN AIR CARRIER.
B. PLANNING. THOSE PERSONS DESCRIBED IN PARAGRAPH A PLANNING TO
OPERATE WITHIN 200 NAUTICAL MILES OF THE OSTT FIR SHOULD EXERCISE
CAUTION AND MUST REVIEW CURRENT SECURITY/THREAT INFORMATION AND
NOTAMS AND COMPLY WITH ALL APPLICABLE FAA REGULATIONS, OPERATIONS
SPECIFICATIONS, MANAGEMENT SPECIFICATIONS, AND LETTERS OF
AUTHORIZATION, INCLUDING UPDATING B450.

C. OPERATIONS. EXERCISE CAUTION DURING FLIGHT OPERATIONS IN THE ABOVE NAMED AREA DUE TO HEIGHTENED MILITARY ACTIVITY IN OR AROUND SYRIA AND THE POTENTIAL RISK TO U.S. CIVIL AVIATION IN THE REGION. THOSE PERSONS DESCRIBED IN PARAGRAPH A MUST REPORT ANY

SAFETY/SECURITY INCIDENTS TO THE FAA AT ASH-AXE-CITE-WATCH FAA.GOV OR +1 202-267-3333 OR 1-844-412-1794.

ADDITIONAL INFORMATION IS PROVIDED AT:

HTTPS://WWW.FAA.GOV/AIRTRAFFIC/PUBLICATIONS/USRESTRICTIONS/
F) SFC G) UNL

PUBLISHED BY US AUTHORITY

************END OF LIDO REMARK*********

1A1825/17

TAKING INTO CONSIDERATION THE ARMED CONFLICT SITUATION IN THE SYRIAN ARAB REPUBLIC, CAA DRAWS YOUR ATTN TO THE POSSIBLE EXISTENCE

OF SERIOUS RISK TO THE SAFETY OF INTL CIVIL FLT OPS IN PORTIONS OF THE BAGHDAD, DAMASCUS AND TEHRAN FIR'S. IT IS RECOMMENDED THAT ALL OPR TAKE ANY AVBL INFO INTO ACCOUNT IN THEIR RISK ASSESSMENTS AND ROUTING DECISIONS IF PLANNING TO FLY INTO, OUT OF, WITHIN OR OVER THE IRAN (ISLAMIC REPUBLIC OF), IRAQ, AND THE SYRIAN ARAB REPUBLIC AIRSPACES.

******LIDO REMARK*****

NOTAM PUBLISHED BY SOUTH AFRICA

*****END OF LIDO REMARK*****

1B261/19

SECURITY SYRIA POTENTIALLY HAZARDOUS SITUATION - FIR DAMASCUS (OSTT) CONTENT:

FEDERAL REPUBLIC OF GERMANY PROHIBITS CIVIL GERMAN AIR OPERATORS TO

PLAN AND CONDUCT FLIGHTS WITHIN FIR DAMASCUS (OSTT). POTENTIAL RISK

TO AVIATION DUE TO A STATE OF WAR INCLUDING MILITARY OPERATIONS. EMERGENCY SITUATIONS: IN AN EMERGENCY THAT REQUIRES IMMEDIATE DECISION AND ACTION FOR THE SAFETY OF THE FLIGHT, THE PILOT IN COMMAND MAY DEVIATE FROM THIS NOTAM TO THE EXTENT REQUIRED BY THAT EMERGENCY.

FURTHER INFORMATION: WEBSITE OF THE FEDERAL MINISTRY OF TRANSPORT AND DIGITAL INFRASTRUCTURE OF GERMANY

(HTTPS://WWW.BMVI.DE/DE/THEMEN/MOBILITAET/LUFT/KRISENMANAGEMENT/KRISENMANAGEMENT.HTML).

*******LIDO RMK******

NTM PUBLISHED BY ED

*****END OF LIDO RMK****

1V3/19

AIRSPACE SECURITY WARNINGS ISSUED BY THE DEPARTMENT FOR TRANSPORT IN RESPONSE TO HAZARDOUS SITUATIONS WITHIN THE TERRITORY AND/OR AIRSPACE OF AFGHANISTAN, EGYPT, IRAQ, KENYA, LIBYA, MALI, NORTH KOREA, PAKISTAN, SOMALIA, SOUTH SUDAN, SYRIA, UP TO 200NM OUTSIDE THE DAMASCUS FIR, UKRAINE AND YEMEN. ALL OPERATORS ARE TO REFER TO THE TABLE IN UK AIP AT ENR 1.1 SECTION 1.4 FOR FURTHER DETAILS. 2018-03-0229-AS6

F) SFC G) UNL

***********LIDO REMARK*********

NOTAM PUBLISHED BY THE UNITED KINGDOM
******END OF LIDO REMARK**********

LCCC NICOSIA FIR

1A356/18

RECENTLY, GPS SIGNAL INTERRUPTIONS HAVE BEEN REPORTED BY THE PILOTS OF THE AIRCRAFT OPERATING WITHIN SOME PARTS OF NICOSIA FIR. AIRCRAFT OPERATORS OPERATING WITHIN NICOSIA FIR ARE ADVISED TO EXERCISE CAUTION.

1A340/10

ALL FLIGHT CREWS ARE KINDLY REQUESTED WHENEVER THEY NOTICE A FOREST FIRE WHILE FLYING OVER CYPRUS TO REPORT IT TO NICOSIA ACC OR LARNAKA AND PAFOS CONTROL TOWERS IMMEDIATELY

AWACS FLIGHT N3745E03730

1A7671/18

AIRBORNE EARLY WARNING AND CONTROL SYSTEM (AWACS) FLIGHT WILL TAKE PLACE AREA: 374500N0373000E 382500N0373000E 382500N0393500E 374500N0373000E

F) FL300 G) FL300

LT A7527/18

1A7527/18

AIR DEFENCE ZONE ESTABLISHED WITH THE FOLLOWING COORDINATES:

AREA: 373236N0364918E 373046N0365223E 373012N0365640E

373132N0370017E 373349N0370225E 373614N0365529E 373236N0364919E 373236N0364918E.

THE SUBJECT ZONE ${f CLOSED}$ TO ALL TRAFFIC EXCEPT OPERATING TO / FROM KAHRAMANMARAS, LTCN, AIRPORT.

FLIGHTS OPERATING TO / FROM KAHRAMANMARAS, LTCN, AIRPORT THROUGH THIS AREA SHALL BE CONDUCTED ACCORDING TO THE PROCEDURES DEFINED BELOW:

1-VFR FLIGHTS (EXCEPT AMBULANCE, FIRE-FIGHTING FLIGHTS AND ORA-OUICK

REACTION AIRCRAFT, GENERAL DIRECTORATE OF SECURITY) NOT ALLOWED IN THE $\ensuremath{\mathsf{ADZ}}$

2-THE WARNINGS TO BE INSTRUCTED BY KAHRAMANMARAS ATC ON FREQUENCIES

118.75, 120.6, 278.625, 121.5 AND 243.00 MHZ SHALL BE CAREFULLY FOLLOWED BY THE FLIGHT CREW OPERATING THROUGH THE ADZ AS IT IS VITALLY IMPORTANT FOR THE FLIGHT SAFETY AND SECURITY. ANY AIRCRAFT HAVING RADIO FAILURE NOT ALLOWED IN THE ADZ.

3-TRANSPONDER OF THE AIRCRAFT OPERATING THROUGH THE ADZ SHALL BE ON

AND **ACTIVE.** ANY AIRCRAFT WITHOUT TRANSPONDER OR HAVING A FAILURE IN

THE TRANSPONDER NOT ALLOWED IN THE ADZ.

4-IFR TRAFFIC OPERATING THROUGH THE ADZ SHALL LEAVE THE ADZ AS SOON

AS POSSIBLE BY THE ATC INSTRUCTION 'LEAVE THE ZONE' OR CONTINUE TO APPROACH AND LAND IF THEY ARE IN THE FINAL APPROACH PHASE OF THE FLIGHT. THE FLIGHTS FLYING OUTSIDE OF THE ADZ ARE NOT ALLOWED TO ENTER THE ADZ WHEN THE ABOVE MENTIONED ATC INSTRUCTION TRANSMITTED.

IF REQUIRED ATC MAY ALSO DELAY THE DEPARTURE TRAFFIC.

5-THE RESPONSIBILITY OF THE SEPARATION OF THE AIRCRAFT WITH THE OTHER AIRCRAFT AND OBSTRUCTIONS SHALL BE PROVIDED BY THE AIR CREW

AS SOON AS THEY ARE INSTRUCTED BY ATC INSTRUCTION 'LEAVE THE ZONE' 6-THE AIRCRAFT OPERATORS PLANNING TO OPERATE THROUGH THE ADZ SHALL DEFINE THE CONTINGENCY PROCEDURES FOR LEAVING THE ADZ AND ENSURE THE FLIGHT CREW ARE INFORMED.

F) SFC G) FL450

AIR REF N375000 E0371850

1A7667/18

AIR REFUELLING WILL TAKE PLACE.

AREA:375000N0371850E 375000N0384300E 371500N0384300E 371500N0371850E

THE AREA CLOSED TO TRAFFIC BTN FL150-FL270

F) 15000FT AMSL G) 27000FT AMSL

TOMBI TOMBI

1A2950/13

NAVIGATIONAL WARNING TO ALL CONCERNED

ALL AIRCRAFT TO ENTER TURKISH AIRSPACE VIA TOMBI OR VESAR ENTRY/EXIT

POINTS, UNTIL THEY ARRIVE THE SUBJECT POINTS, SHALL CONTACT TO ANKARA

ACC THROUGH 127.85,128.75,130.4,124.075 MHZ OR THE EMERGENCY CHANNELS.

ANY AIRCRAFT NOT CONTACT TO ANKARA ACC UNTIL REACHING TO THE TOMBI OR VESAR ENTRY/EXIT POINTS SHALL NOT BE PERMITTED TO ENTER TURKISH AIRSPACE.REF NOTAM A2948/13

1A2948/13

NAVIGATIONAL WARNING

1A1133/12

DUE TO THE SHUTTING DOWN OF THE DIRECT COMMUNICATION LINE BY

DIRECT COMMUNICATION AND COORDINATION BETWEEN ANKARA AND NICOSIA AREA CONTROL CENTRES CAN NOT BE EFFECTED, THEREFORE: A. AIRCRAFT INBOUND TO NICOSIA FIR FROM ANKARA FIR SHALL ESTABLISH RADIO CONTACT WITH NICOSIA ACC IN ORDER TO PASS ESSENTIAL FLIGHT DETAILS (CALLSIGN, FL, ETO ENTRY POINT) ON FREQUENCY 125.5 FOR TOMBI AND 126.3 FOR VESAR AND DOREN, 10 MINUTES PRIOR TO ENTRY.


B. AIRCRAFT INBOUND TO ANKARA FIR FROM NICOSIA FIR SHALL PASS FLIGHT DETAILS TO ANKARA ACC BEFORE ENTERING ANKARA FIR 1N78/06


NAVIGATIONAL WARNING


IN ORDER TO ENSURE NAVIGATIONAL SAFETY AND IN CONSIDERATION OF ADDITIONAL SENSITIVITY IN THE REGION, ALL AIRCRAFT WITHIN ERCAN ADVISORY AIRSPACE TO ENTER ANKARA FIR VIA TOMBI OR VESAR SHALL ESTABLISH CONTACT WITH ERCAN CONTROL ON 126.7 MHZ OR EMERGENCY CHANNELS.

PGT 2096/22 APR/SAW-ADA A/C: TCNBF	Page 24
LT A0873/19	
1A873/19 SR-SS AREA LTC3 (ANTALYA-TAHTALIDAGI), AIRSPACE RESERVATION ACTIVATION REF AIP ENR 5.5-2 F) SFC G) 7800FT AMSL	ATED.
======================================	======

PGT 2096/22 APR/SAW-ADA A/C: TCNBF	Page 25
[Company NOTAM]	
======= CREW ALERT	
CO5/19 COMPANY NOTAM IMPORTANT NOTICE ABOUT CAT-IIIB OPERATIONS : COMPANY CAT-IIIB APPROVAL PROCESS HAS BEEN STARTED BUT NOT COMPLETED YET. YOU INFORMED WHEN OUR COMPANY AUTHORIZED BY TURKISH DGCA FOR CAT- APPROACHES. UNTIL THE NEXT ANNOUNCEMENT, CAT-IIIB APPROACHES NOT BE PERFORMED UNDER REAL LOW VISIBILITY CONDITIONS.	WILL BE IIIB
======================================	
======= END OF LIDO-COMPANY-NOTAM-BULLETIN =======	====







PGT 2096/22 APR/SAW-ADA A/C: TCNBF Page 29

[RAIM Briefing]

FUEL ADVISORY:

THERE ARE NO RAIM OUTAGES FOR THE PLANNED APPROACHES

RAIM BRIEFING

LTFJ --> LTAF PC2096 / 22-Apr-19

VALID: 22-Apr-19 17:45 - 22-Apr-19 22:36

MINIMUM NUMBER OF HEALTHY SATELLITES: 31

DURING VALIDITY OF THE BRIEFING PACKAGE FOLLOWING RAIM OUTAGES EXIST

DESTINATION ALTERNATE(S)

LTAJ / GZT GAZIANTEP

PRECISION BARO AIDED MASK ANGLE OUTAGE RNP 0.30 yes 5.0 NO OUTAGES RNP 0.30 5.0 5.0 yes RNP 1.00 5.0 NO OUTAGES yes

LTAU / ASR KAYSERI

PRECISION BARO AIDED MASK ANGLE OUTAGE 5.0 NO OUTAGES RNP 0.30 yes RNP 1.00 5.0 NO OUTAGES yes

ENROUTE AIRPORT(S)

LTFH / SZF SAMSUN/CARSAMBA

PRECISION BARO AIDED MASK ANGLE OUTAGE RNP 0.30 yes 5.0 NO OUTAGES 5.0 5.0 yes RNP 1.00 yes NO OUTAGES