



THE REPUBLIC OF LIBERIA
LIBERIA MARITIME AUTHORITY

8619 Westwood Center Drive
Suite 300
Vienna, Virginia 22182, USA
Tel: +1 703 790 3434
Fax: +1 703 790 5655
Email: security@liscr.com
Web: www.liscr.com

05 April 2016

Marine Security Advisory: 01/2016

(This Advisory supersedes Marine Security Advisory 3/2015)

Subject: U.S. Coast Guard Revises Security Advisory Regarding Ports Not Maintaining Effective Anti-Terrorism Measures

Reference: (a) USCG Port Security Advisory (1-16) – ATTACHED

Dear Shipowner/Operator/Master;

Update:

The U.S. Coast Guard has issued the attached Port Security Advisory (1-16). In Port Security Advisory 1-16 the US Coast Guard has determined that the Republic of Cuba is now maintaining effective anti-terrorism measures in their ports. The Republic of Cuba is removed from the list of the Countries Affected in paragraph B of this Port Security Advisory. Therefore, actions required in paragraphs C and D of this Port Security Advisory are no longer required for vessels that arrive in the United States after visiting ports in the Republic of Cuba.

Note: Department of the Treasury Office of Foreign Asset Control travel restrictions to Cuba remain in effect and regulations regarding "Unauthorized Entry into Cuban Territorial Waters", located at 33 C.F.R. § 107.200 et seq, still apply.

All vessels that visited the countries/facilities listed in paragraph B of the USCG Advisory (with exceptions noted) during their last five port calls will be boarded or examined at sea by the Coast Guard to ensure required actions were taken. Failure to properly implement the actions listed in paragraph C.1 through C.5 of the attached advisory may result in delay or denial of entry into the United States.

Vessel security actions:

Effective immediately ALL Liberian registered vessels while in ports of the countries noted in the attached USCG Port Security Advisory (1-16) shall:

1. Implement measures as per the ship's security plan equivalent to Security Level 2 and
2. Take the required actions listed in section C of the attached advisory including attempting to execute a Declaration of Security (DOS).

Reminder: No vessel shall operate at a Security Level lower than that of a port facility. Additionally, the Master has the overriding authority to increase the Security Measures of the vessel at any time to protect the safety and security of the vessel.

For more information please contact the Security Department at telephone + 1 703 790 3434, email security@liscr.com; LISCAR Duty Officer + 1 703 963 6216, email dutyofficer@liscr.com

* * * * *



Port Security Advisory (1-16)

A. Background:

The Maritime Transportation Security Act of 2002 (MTSA) has mandated that the United States Coast Guard evaluate the effectiveness of anti-terrorism measures in foreign ports and provides for the imposition of conditions of entry on vessels arriving to the United States from countries that do not maintain effective anti-terrorism measures (MTSA, 46 U.S.C. §§ 70108 - 70110).

The Coast Guard has determined that the Republic of Cuba is now maintaining effective anti-terrorism measures in their ports. The Republic of Cuba is removed from the list of the Countries Affected in paragraph B of this Port Security Advisory. Therefore, actions required in paragraphs C and D of this Port Security Advisory are no longer required for vessels that arrive in the United States after visiting ports in the Republic of Cuba.

Note: Department of the Treasury Office of Foreign Asset Control travel restrictions to Cuba remain in effect and regulations regarding "Unauthorized Entry into Cuban Territorial Waters", located at 33 C.F.R. § 107.200 et seq, still apply.

B. Countries Affected:

The Coast Guard has determined that ports in the following countries are not maintaining effective anti-terrorism measures:

Cambodia

Cameroon

Exceptions	IMO Port Number
Ebome Marine Terminal	CM394-0001
Quai GETMA (LAMNALCO Base) Facility	CMDLA-0005
Société Nationale de Raffinage (SONARA) Terminal (also known as Cap Limboh Terminal)	CMLIT-0001
Kome-Kribi 1	CM234-0001
Douala International Terminal (also known as Douala Containers)	CMDLA-0002
Moudi Terminal	CMMOU-0001

Comoros

Cote d' Ivoire



Equatorial Guinea

Exceptions	IMO Port Number
Ceiba	GQ362-0001/0002
K-5 Oil Center	IMO number not listed
Luba	GQLUB-0001
Punta Europa Terminal	GQ368-0001
Zafiro Marine Terminal	GQ370-0001

The Gambia

Guinea-Bissau

Iran

Liberia

Exceptions	IMO Port Number
Firestone Facility	IMO number not listed;
Port of Monrovia	LRMLW-0001

Libya

Note: Vessels are also advised to proceed with extreme caution when approaching all Libyan oil terminals, particularly in eastern Libya, due to potential violent and criminal activity based upon recent attempts by armed, non-state actors to engage in illicit export of oil. UN Security Council Resolution 2146 authorizes the UN Sanctions Committee to impose certain measures on vessels attempting to illicitly export crude oil from Libya. This resolution imposes several restrictions regarding loading, transporting, or discharging crude oil from Libya which may include the possible denial of port entry. Further information regarding the UN Security Council Resolution can be found at:

<http://www.un.org/News/Press/docs//2014/sc11325.doc.htm>

Madagascar

Exceptions	IMO Port Number
Toamasina (also known as Tamatave)	MGTMM-0001

Nigeria

Exceptions	IMO Port Number
APP Apapa Bulk Terminal	NGAPP-0009
APP AP Moller Terminal	NGAPP-0001
APP Greenview Terminal	NGAPP-0004
BON Bonny River Terminal	NGBON-0001
BON NLGN Bonny Terminal	NGBON-0002
BON SPDC Bonny Offshore Terminal	NG663-001
BON NLGN Bonny Terminal	NGBON-0002
BON SPDC Bonny Offshore Terminal	NG663-001
CBQ FSO YOHO (Exxon Mobile)	NG638-0001



CBQ Logistics Base	NGCBQ-0001
CBQ McIver Wharf	NGCBQ-0004
CBQ Port Terminal A	NGCBQ-0002
CBQ QIT BOP	NGOBO-0001
ESC Escra BOP	NGESC-0001
ESC LPG-FSO	NGESC-0003
FOR Forcados Offshore Terminal	NGFOR-0001
ONN FLT	NGONN-0005
ONN FOT	NGONN-0006
TIN Dantata MRS Terminal	NGTIN-0003
TIN FSL	NGTIN-0013
TIN P&CH Terminal C	NGTIN-0011
TIN Snake Island Integrated Free Zone	NGTIN-0001
TIN PTML Terminal E	NGTIN-0010
TIN TICT Terminal B	NGTIN-0009

Sao Tome and Principe

Syria

Timor-Leste

Venezuela

Yemen

Exceptions	IMO Port Number
Balhaf LNG Terminal NOTE: The U.S. Coast Guard has separate, more stringent security protocols in place for vessels arriving to the United States from Balhaf. Vessels planning to arrive to the United States from Balhaf should contact the cognizant U.S. Coast Guard Captain of the Port well in advance.	IMO number not listed

C. Actions Required by Vessels Visiting Countries Affected:

All vessels arriving to the United States that visited the countries listed in paragraph B (with exceptions noted) during their last five port calls must take actions 1 through 5 listed below while in the countries listed in paragraph B as a condition of entry into U.S. ports:

1. Implement measures per the ship's security plan equivalent to Security Level 2;
2. Ensure that each access point to the ship is guarded and that the guards have total visibility of the exterior (both landside and waterside) of the vessel. Guards may be:



- provided by the ship's crew, however, additional crewmembers should be placed on the ship if necessary to ensure that limits on maximum hours of work are not exceeded and/or minimum hours of rest are met, or
 - provided by outside security forces approved by the ship's master and Company Security Officer.
3. Attempt to execute a Declaration of Security;
 4. Log all security actions in the ship's security records; and
 5. Report actions taken to the cognizant U.S. Coast Guard Captain of the Port prior to arrival in the U.S.

Vessels that visited the countries listed in paragraph B (with exceptions noted) on or after the effective date in paragraph A, during their last five port calls will be boarded or examined by the Coast Guard to ensure the vessel took the required actions. Failure to properly implement the actions listed in paragraph C.1 through C.5 may result in delay or denial of entry into the United States.

D. Actions Required by Vessels in U.S. Ports:

Based on the findings of the Coast Guard boarding or examination, the vessels that visited the countries listed in paragraph B (with exceptions noted) on or after the effective date in paragraph A **may** be required to ensure that each access point to the ship is guarded by armed security guards and that they have total visibility of the exterior (both landside and waterside) of the vessel while in U.S. ports. The number and location of the guards must be acceptable to the cognizant U.S. Coast Guard Captain of the Port. For those vessels that have demonstrated good security compliance and can document that they took the measures called for in C.1. through C.4. above, the armed security guard requirement will normally be waived.

###