

Palau International Ship Registry



Europe Head Office
Piraeus, 18536, Greece
5, Sachtouris Street
6th floor
T: +30 210 4293500
F: +30 210 4293505
info@palaureg.com

USA Head Office
The Woodlands, TX, 77380
9595 Six Pines Drive,
Suite 8210, Office 277
T: +1 832 631 6061
F: +1 832 631 6001
www.palaureg.com

MARINE CIRCULAR 147.1

To: RECOGNIZED SECURITY ORGANIZATIONS, SHIPOWNERS, MANAGERS, OPERATORS, MASTERS, COMPANY SECURITY OFFICERS, SHIP SECURITY OFFICERS, DEPUTY REGISTRARS.

Subject: ANTI-PIRACY SECURITY MEASUREMENTS TO BE TAKEN IN URGENT BASIS IN GULF OF OMAN AND ADJACENT AREAS

1. Reference

- 1.1 SOLAS 74/78 Chapter XI-2

2. Purpose

- 2.1 The purpose of this Marine Circular is to communicate the need for imperative anti-piracy security measurements to be taken in urgent basis in Gulf of Oman and adjacent areas.

3. Applicability

- 3.1 This Marine Circular applies to all Palau registered ships trade and/or transit in the Gulf of Oman area.

4. General Information

- 4.1 Palau Ship Registry Administrator strongly recommends to all the shipowners/managers and/or operators of the Palau flagged vessels to keep the proper anti-piracy security measures on board in order to reduce the likelihood of being attacked by pirates, in the aforementioned areas, considering the recent attacks that have taken place showing that the level of threats have been risen in the last days, as per the recent communication given by the Secretary General of the International Maritime Organization (IMO).
- 4.2 PISR urges Companies, Company Security Officers (CSO), Ship Security Officers (SSO) of Palau flagged vessels, to implement the necessary security measures described in the latest edition of the Best Management Practices BMP, before, during and after the transit through Gulf of Oman
- 4.3 All the Palau flagged vessels whether using or not the services of Private Maritime Security Companies shall maintain a wide communication with the Palau Ship Registry Administrator and to liaise with the International Contact Centers according to the BMP in order to counter piracy in the area before, during and after transit.



Palau International Ship Registry



Europe Head Office
Piraeus, 18536, Greece
5, Sachtoura Street
6th floor
T: +30 210 4293500
F: +30 210 4293505
info@palaureg.com

USA Head Office
The Woodlands, TX, 77380
9595 Six Pines Drive,
Suite 8210, Office 277
T: +1 832 631 6061
F: +1 832 631 6001
www.palaureg.com

- 4.4 For this reason, we strongly encourage to all the Palau flagged vessels to complete and submit the “Vessel Position Reporting Form” to UMKTO, MARLO and the “Vessel Movement Registration Form” to MARLO, both described in the latest edition of the Best Management Practices (BMP) prior to entering the aforementioned area. All the available local information centers shall be also contacted for up to date instructions or transit and reporting.
- 4.5 The Palau Ship Registry Administrator encourage all operators, managers, owners, CSOs of Palau flagged vessels, to contact the International Maritime Bureau (IMB) Piracy Reporting Center 24/7, in case of any incident of piracy or attack that occurs in any part of the country world. Captains of the vessels are requested to display information of IMB to various areas of the vessel.
- 4.6 All the Palau flagged vessels transiting through Gulf of Oman and nearby areas have to raise their Security Level according to their Ship Security Plan.
- 4.7 All the Palau flagged vessels under SOLAS V/19-1 regulation are required to comply with LRIT requirement. The LRIT system must work properly as the ships are transiting the area. This ensures the possibility to track vessels and will allow detecting any unexpected change of course or any other suspicious situation.

5. Contact

- 5.1 Any inquiries concerning the subject for this Marine Circular should be directed to the Palau Ship Registry Administrator at technical@palaureg.

Click [here](#) or use the below QR Code
for the list of the last updated Marine
Circulars

