LabNotebook

Bijan Varjavand

November 29, 2016

1 Introduction

1.1 Goals

generate a temperature vs toughness graph

- 2 Purpose
- 3 Setup

3.1 Materials

1018 steel as received (not annealed)

3.2 Tools

Pendulum for impact testing Furnace (at $200^o\mathrm{C}$ and $100^o\mathrm{C})$

- 4 Procedure
- 4.1 Charpy Test
- 5 Results
- 6 Observations