




# Full Mission PSD Intensity Trends




# Latest PSD Intensity Trends







# Full Mission Min/Max PSD and Laser Temperatures




# PSD Laser Off Intensity




# PSD0 Laser Off 1- $\sigma$ Noise




# PSD0 Laser On 1- $\sigma$ Noise




PSD0 Laser Off 1- $\sigma$  Noise




# PSD1 Laser On 1- $\sigma$ Noise




# PSD0 Laser On - Laser Off




# PSD1 Laser On - Laser Off






# PSD1 Laser Off Intensity



# Laser Intensity vs Laser Housing Mean Temperatures



# Laser Intensity vs Maximum Housing Temperatures

