




# Full Mission PSD Intensity Trends




# Latest PSD Intensity Trends




# Full Mission PSD and Laser Temperatures




# Full Mission Min/Max PSD and Laser Temperatures




# PSD Laser Off Intensity




# PSD0 Laser Off 1- $\sigma$ Noise




# PSD0 Laser On 1- $\sigma$ Noise




# PSD0 Laser Off 1- $\sigma$ Noise




# PSD1 Laser On 1- $\sigma$ Noise




# PSD0 Laser On - Laser Off




# PSD1 Laser On - Laser Off




# PSD0 Laser Off Intensity



# PSD1 Laser Off Intensity



# Laser Intensity vs Laser Housing Mean Temperatures



# Laser Intensity vs Maximum Housing Temperatures

