0	1	2	3	4	5		6	7		8	8		9]
Alteration No.	Alteration	Sign.,year,month entered		Denna handling får ej utan vårt medgivande kopieras, delgivas			CIRCUIT		ر ا	115 40/	^	1 00	1 00	
				annan eller eljest obehörigen användas. Överträdelse beivras	/ ////		PROCESS	OPTION	3	HEAO	02381	L-00	1 00	4
				med stöd av gällande lag. This document must not without			AWC		туре ІК	C5 D20	006 scale		ode K1R	
				our permision be copied, im- parted to a third party or other-		Week D	Design checked Accepted for prod. by	Drawing checked by	Drawn by		Projekt	Location	Sheet 1	1
				wise unathorizedly used. Con- tranvention will be prosecuted.	06	21	RAW/BA		RAWB/AN				cont. 2	1
				ABB Flexible Automation AB										١

DIRECTORY

PAGE	COMMENTS
/1	DIRECTORY
/2	BLOCK DIAGRAM
/3	MAINS
/4	AUXILIARY TRANSFORMER
/5	AWC SENSORS
/7	CAN DISTRIBUTION











