1 2 3 4 5 6 7



The information in this document is subject to change without notice and should not be construed as a commitment by ABB. ABB assumes no responsibility for any errors that may appear in this document.

Except as may be expressly stated anywhere in this document, nothing herein shall be construed as any kind of guarantee or warranty by ABB for losses, damages to persons or property, fitness for a specific purpose or the like.

In no event shall ABB be liable for incidental or consequential damages arising from use of this document.

This document and parts thereof must not be reproduced or copied without ABB's written permission, and contents therof must not be imparted to a third party nor be used for any unauthorized purpose. Contravention will be prosecuted.

Additional copies of this document may be obtained from ABB at its then current charge.

© Copyright 2004 ABB ALL right reserved.

ABB Automation Technologies AB
Robotics
SE-721 68 Västerås
Sweden

Latest revision: ECO 80624, WI 106464

breserve all rights in this document and in the information contained therein. Reproduction, use disclosure to third parties without express authority is strictly forbidden. © Copyright 2003 ABB

Page 10: Connection R1.MP:13 to X8:2 added.

| ABB

DMRO SE/ Manipulator circuit diagram

COPYRIGHT page

Status: 2016-05-03

APPROVED

Plant: = IRB 2600 Location: + Manipulator

APPROVED |SI

Sublocation:+

| Rev. Ind | Page1 |

Prepared by, date: Erik Mesaros | Approved by, date: JanErik Nåhls

3HAC029570-007

05 Next 2 Total 19

Table of contents ABB Contents1 Page description Page Comment COPYRIGHT page 2 Table of contents: (1 - 110) 3 Valid For 4 Connection point location 5 Legend 10 Brake Release Unit 20 Serial Measuring Board Incl. optional cable harness axis 7 30 Axis 1 Incl. optional cooling fan 1 40 Axis 2 Incl. optional cooling fan 2 50 Axis 3 60 Axis 4 70 Axis 5 71 Axis 5, IRB 2600ID 80 Axis 6 Incl. optional signal lamp 81 Axis 6, IRB 2600ID 90 Customer connection (CP) 100 Customer connection (CS) 110 Multibus 120 **Profibus** riant: = IRB 2600 Location: + Manipulator Sublocation:+ Lab/Office: DMRO SE/ PRMP Status: 2016-05-03 Latest revision: ECO 80624, WI 106464 ABB Manipulator circuit diagram Page 10: Connection R1.MP:13 to X8:2 added. **APPROVED** Table of contents: (1 - 110) Document no. 3HAC029570-007

We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express authority is strictly forbidden. © Copyright 2003 ABB

Prepared by, date: Erik Mesaros Approved by, date: JanErik Nåhls

Rev. Ind Page2
Next 3
Total 19

5 6 Valid for: This circuit diagram is valid for the following cable harnesses assemblies: 1) 3HAC030006-001 Cable harness, basic. 2) 3HAC4050-1 Signal cable SMB. 3) 3HAC030936-001 Cable harness ax.7. 4) 3HAC035054-001 Lamp unit. 5) 3HAC035037-001 Cooling fan for ax.1 and ax.2. 6) 3HAC029896-001 Cable harness, customer connection. 7) 3HAC030006-001 Cable harness, basic. 8) 3HAC030007-001 Cable harness, multibus. 9) 3HAC035547-001 Cable harness, IRB 2600ID. 10) 3HAC037799-001 Cable harness, profibus. We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express authority is strictly forbidden. © Copyright 2003 ABB Lab/Office: DMRO SE/ PRMP Status: 2016-05-03 = IRB 2600 Plant: Latest revision: ECO 80624, WI 106464 ABB Manipulator circuit diagram Location: + Manipulator
Sublocation:+ Page 10: Connection R1.MP:13 to X8:2 added. APPROVED Valid For Document no.


Prepared by, date:

Erik Mesaros Approved by, date: JanErik Nåhls


Rev. Ind Page3 Next 4

3HAC029570-007


05 Total 19



R1.MP



R1.CP/CS



R1.CBUS



Prepared by, date: Erik Mesaros Approved by, date: JanErik Nåhls IRB 2600


Status: 2016-05-03


3HAC029570-007

Plant:

= IRB 2600 Location: + Sublocation:+ + Manipulator

Rev. Ind Page4
Next 5 Total 19








Prepared by, date:

Erik Mesaros Approved by, date: JanErik Nåhls

05 Total 19









Prepared by, date: Erik Mesaros Approved by, date: JanErik Nåhls


IRB 2600


3HAC029570-007


Rev. Ind Page40
Next +Axis 3 05 Total 19

















-Customer connection cable -R1.CP/CS -R2.CS WHBN CSA WHRD CSB CSC **WHOG WHYE** CSD WHGN CSE WHBU CSF WHVT CSG WHGY CSH We reserve all rights in this document and in the information contained therein. Reproduction, use or disclosure to third parties without express authority is strictly forbidden. © Copyright 2003 ABB **GYBK** CSJ **GYBN** CSK **GYRD** CSL <u>b11</u> GYOG CSM **GYYE** CSN **GYGN** CSP **GYBU** CSR b15 **GYVT** CSS **GYWH** CST **GNBK** CSU **GNBN** CSV GNRD CSW b21 b22 **GNOG** CSX **GNBU** CSY b23 **GNVT** CSZ b24 ÷ \pm Lab/Office: DMRO SE/ PRMP Status: 2016-05-03 = IRB 2600 Plant: Latest revision: ECO 80624, WI 106464 Manipulator circuit diagram Location: + CP/CS Page 10: Connection R1.MP:13 to X8:2 added. **APPROVED** Sublocation:+ Customer connection Rev. Ind Page 100
Next + Multib Document no. 3HAC029570-007 Prepared by, date: Erik Mesaros Approved by, date: JanErik Nåhls Total 19

4

5

6

