


0	1	2	3	4	5			6	7	,		3	9	
Alteration No.	Alteration	Sign., year, month entered		Denna handling får ej utan vårt medgivande kopieras, delgivas			<u> </u>		DIAGRAN	1 2	$\Box \Box \Lambda Q I$	00729	001	01
5xx26685 Sh.3	New LB added	AN, 07, 11		annan eller eljest obehörigen användas. Överträdelse beivras			ノ <u> SA</u>	FETY C	PTIONS		ПЕАО	<u> </u>	1-00T	. ОТ
				med stöd av gällande lag. This document must not without			В/	c/ci/c)/K/R	туре \mathbf{I} \mathbf{F}	RC5	scale	Code	K1R
				our permision be copied, im- parted to a third party or other-	Year	week	Design checke	d Accepted for prod. by	Drawing checked by	Drawn by		Projekt	Location 5	Sheet 1
				wise unathorizedly used. Con- tranvention will be prosecuted.	07	45	PRMW/B	A PRMW/A		PRMW/AN			(Cont. 2
				ABB Flexible Automation AB Welding Systems										


DIRECTORY

PAGE	COMMENTS
/1	DIRECTORY
/2	BLOCK DIAGRAM
/3	OPTION GUARD EQUIPMENT LIGHT BEAM MSLZ & M4000/M40Z
/4	OPTION RESET PROTECTION -PRE RESET PB
/5	OPTION SERVICE DOOR SUPERVISION









PRE RESET PUSH BUTTON

