



# SERVICE BULLETIN

QUALITY INFORMATION ANALYSIS

OVERSEAS SERVICE DEPT. MITSUBISHI MOTORS CORPORATION

<b>SERVICE BULLETIN</b>		No.: MSB-99E11-003	
		Date: 2000-05-31	<Model>
<b>Subject:</b> CHANGE IN 4G1 ENGINE CRANKSHAFT PULLEY			<M/Y>
<b>Group:</b> ENGINE	Draft No.:	99EN573119	

**INFORMATION/**