


Q#1:





Q#2: The axial loads are not in the safe window.



Q#3: At 22000lbs we are in the safe window for over pulling instead of 40000.

