


Contact persistence is not receiver validation



Blue: positive normal contact. Geometry, overlap and unsupported wrench must also be considered.