


Native actuator response during startup

CENSORED STARTUP: stopped at 4 ms; planned 3 s ramp/hold was not reached. No extrapolation.

IMP99



TC10_IMP99

