

No simultaneous M/R/L contact before force stop

CENSORED STARTUP: stopped at 4 ms; planned 3 s ramp/hold was not reached. No extrapolation.

