


Corrected command sweep: no sustained calibration contact



Frozen 10 offsets; existing actuator targets + existing object fixture; 100-ms settle, last 20-ms mean.