
(a) Conflict pair-steps
C
0
2
4
6
8
Uncoordinated A*
n = 20/20
Safe serial
n = 20/20
Coordinated
n = 20/20
(b) Valid makespan
T makespan (steps)
0
20
40
60
80
Uncoordinated A*
n = 2/20
Safe serial
n = 20/20
Coordinated
n = 20/20
(c) Planning time
T plan (ms)
0
20
40
60
80
100
Uncoordinated A*
n = 20/20
Safe serial
n = 20/20
Coordinated
n = 20/20
(d) Wait steps
N wait (steps)
0
2
4
6
8
10
Uncoordinated A*
n = 20/20
Safe serial
n = 20/20
Coordinated
n = 20/20