











TSP Week 9 Quiz

1. The part may not fit its purpose and be effectively useless
2. A dimension that is "critical" to the function of the part.
3. With proper use of critical dimensions and checking said dimensions on the physical part match the critical dimensions within a specified tolerance.