


SECTION B–B

NOTES

1. CHAMFER ALL SHOULDERS 1 × 45°.
2. INDUCTION HARDEN BEARING SEATS 50–55 HRC.
3. RUN-OUT OF Ø45 k6 ≤ 0.02 TO A–B.

SAMPLE DRAWING · ENG Drawing Viewer

Fictional part for demonstration. Not for manufacture.

TITLE				DRAWING NO.	
DRIVE SHAFT				**EDV-1003**	
MATERIAL		GENERAL TOLERANCES		REV	SHEET
42CrMo4 +QT		ISO 2768-mK		A	1 / 1
SCALE	SIZE	MASS	UNITS	PROJECTION	
1:2	A3	3.12 kg	mm		