SnagAI - Construction Defect Report

AI-assisted site inspection

Inspection Details

Image file	istockphoto-458080981-1024x1024.jpg
Session ID	19e27373-0d24-443d-be80-d28d1acb8505
Analysed	2026-03-03T11:02:49.742014+00:00
Total issues	5

Site Photo

Issues Found (5)

#	Issue Type	Conf.	Location (bbox)
1	**Other Issue** *Exposed rebar sticking out vertically without any caps or safety measures.*	95%	x=0.03 y=0.25 w=0.15 h=0.25
2	**Other Issue** *Concrete surface shows signs of water pooling and possible inadequate curing.*	85%	x=0.60 y=0.60 w=0.15 h=0.10
3	**Other Issue** *Wood and construction debris scattered on the ground creating potential hazards.*	90%	x=0.00 y=0.15 w=0.30 h=0.20
4	**Other Issue** *Formwork at the bottom left appears incomplete and lacks reinforcement.*	92%	x=0.00 y=0.80 w=0.25 h=0.20
5	**Other Issue** *Workers are positioned near exposed rebar and other site hazards.*	90%	x=0.50 y=0.35 w=0.20 h=0.20