SnagAI - Construction Defect Report

AI-assisted site inspection

Inspection Details

Image file	pexels-monica-3562689.jpg
Session ID	0256e0b4-4ef0-48b1-9bef-67d9382ab426
Analysed	2026-03-03T11:03:09.493827+00:00
Total issues	5

Site Photo

Issues Found (5)

#	Issue Type	Conf.	Location (bbox)
1	**Other Issue** *Exposed rafters and joists visible in the ceiling, indicating missing plasterboard or ceiling tiles.*	95%	x=0.00 y=0.00 w=1.00 h=0.30
2	**Other Issue** *Peeling paint and crumbling plaster on the walls, showing extensive surface damage.*	90%	x=0.00 y=0.30 w=1.00 h=0.70
3	**Other Issue** *Uneven and scratched wooden floorboards with visible dirt and debris.*	85%	x=0.00 y=0.80 w=1.00 h=0.20
4	**Other Issue** *A blue tarp hanging from the ceiling in an unfinished manner.*	80%	x=0.30 y=0.00 w=0.20 h=0.40
5	**Other Issue** *Electrical wire hanging loosely near the wall socket.*	85%	x=0.65 y=0.75 w=0.20 h=0.10