SnagAI - Construction Defect Report

AI-assisted site inspection

Inspection Details

Image file	pexels-reneterp-3990359.jpg
Session ID	e421023d-1abc-469b-9c96-7d152114a959
Analysed	2026-03-03T11:03:44.389029+00:00
Total issues	4

Site Photo

Issues Found (4)

#	Issue Type	Conf.	Location (bbox)
1	**Other Issue** *Two ladders are left unsecured and one is leaning against the wall at an unsafe angle.*	95%	x=0.10 y=0.25 w=0.25 h=0.50
2	**Other Issue** *A level tool is leaning unsecured against a wall, posing a safety risk.*	90%	x=0.22 y=0.30 w=0.08 h=0.40
3	**Other Issue** *Loose wires and debris scattered over the floor create trip hazards.*	85%	x=0.00 y=0.70 w=1.00 h=0.30
4	**Other Issue** *The wall cavity is open and partially unfinished with visible insulation.*	88%	x=0.70 y=0.10 w=0.25 h=0.80