SnagAI - Construction Defect Report

AI-assisted site inspection

Inspection Details

Image file	pexels-pixabay-159358.jpg
Session ID	309028dc-af86-415b-8012-2486a6208d10
Analysed	2026-03-03T12:02:03.371924+00:00
Total issues	6

Annotated Site Photo (box numbers match table rows)

Issues Found (6)

#	Issue Type	Conf.	Location (bbox)
1	**Other Issue** *Multiple sections of vertical reinforcement bars (rebar) are protruding upwards from unfinished concrete columns without any protective caps or coverings.*	98%	x=0.04 y=0.44 w=0.11 h=0.21
2	**Other Issue** *A cluster of exposed vertical rebar is visible near the right side concrete column with no protective caps.*	97%	x=0.93 y=0.46 w=0.05 h=0.21
3	**Other Issue** *Horizontal reinforcement bars are scattered and not properly stacked or tied down on the slab area creating a tripping hazard.*	94%	x=0.08 y=0.18 w=0.22 h=0.30
4	**Other Issue** *A worker is standing on an unsecured metal ladder open to a deep pit or shaft, without any visible stabilization or someone footing the ladder.*	99%	x=0.34 y=0.75 w=0.11 h=0.22
5	**Other Issue** *Loose construction materials including scattered steel bars and wooden planks are left on the working surface, causing potential trip and fall hazards.*	92%	x=0.69 y=0.08 w=0.20 h=0.24
6	**Other Issue** *Waste material and debris are left scattered near the central area of the slab under construction.*	90%	x=0.58 y=0.42 w=0.13 h=0.13