SnagAI - Construction Defect Report

AI-assisted site inspection

Inspection Details

Image file	pexels-reneterp-3990359.jpg
Session ID	33e8d6a2-2a80-4f7b-a620-1f11e0e2aad5
Analysed	2026-03-03T12:02:22.861020+00:00
Total issues	10

Annotated Site Photo (box numbers match table rows)

Issues Found (10)

#	Issue Type	Conf.	Location (bbox)
1	**Other Issue** *A wooden ladder is standing unsecured against the wall, increasing the risk of it falling over.*	98%	x=0.13 y=0.23 w=0.21 h=0.54
2	**Other Issue** *A second wooden ladder is leaning unsecured against the partition wall, posing a fall hazard.*	98%	x=0.36 y=0.18 w=0.12 h=0.53
3	**Other Issue** *A small stepladder is placed on the floor without being secured or footed.*	97%	x=0.46 y=0.67 w=0.14 h=0.22
4	**Other Issue** *Long metal spirit level is leaning against the wall without any support, which could easily fall over.*	96%	x=0.45 y=0.11 w=0.07 h=0.68
5	**Other Issue** *There is visible construction debris and dust scattered across the floor in front of the stepladder.*	95%	x=0.36 y=0.77 w=0.27 h=0.21
6	**Other Issue** *Loose offcuts and debris can be seen scattered on the floor at the entrance to the other room.*	92%	x=0.76 y=0.84 w=0.17 h=0.16
7	**Other Issue** *Loose electrical cables are trailing across the floor, creating trip hazards throughout the room.*	96%	x=0.10 y=0.78 w=0.42 h=0.18
8	**Other Issue** *The doorway has exposed framing and unfinished edges around the door, indicating incomplete finishing work.*	93%	x=0.69 y=0.15 w=0.30 h=0.72
9	**Other Issue** *The floor at the doorway is missing covering and shows exposed, worn subfloor with possible remnants of adhesive or paint.*	91%	x=0.75 y=0.61 w=0.21 h=0.22

10	**Other Issue**	90%	x=0.00 y=0.00 w=1.00 h=1.00
	General poor housekeeping is observed with disorganized tools and materials left on the floor.		