

BAYFRONT PROPERTY INSPECTIONS

Licensed Florida Home & Commercial Inspector — License No. HI-7741

Inspection Date: March 6, 2026

Inspector: Raymond Ostrander

PROPERTY INSPECTED: 4412 Bayshore Blvd, Tampa, FL 33611 (mixed-use, ground-floor retail + second-floor commercial suites)

CLIENT: Marcus Calloway

SUMMARY OF FINDINGS

1. **STRUCTURE / FOUNDATION:** Slab-on-grade foundation observed in satisfactory condition. No significant settlement cracking noted.
2. **ROOFING:** Modified-bitumen flat roof, approximately 12 years old. ****ACTIVE ROOF LEAK** observed above second-floor commercial Unit 2C; visible water staining on ceiling and soft roof decking detected on probe. Estimated repair cost \$18,500. Recommend licensed roofer evaluation prior to closing.** Membrane seams near the rear parapet show ponding and alligatoring.
3. **HVAC:** Two split systems. Unit 1A condenser is at the end of its service life and should be budgeted for replacement. Unit 2C system operational.
4. **ELECTRICAL:** 400-amp service, copper branch wiring. GFCI protection absent at three exterior receptacles — recommend correction.
5. **PLUMBING:** Copper supply, cast-iron drain stacks. Minor corrosion at water-heater fittings.
6. **EXTERIOR / SITE:** Stucco facade in fair condition with hairline cracking. Parking lot striping faded.

This report reflects visual, non-invasive observation only. Latent defects may exist that are not discoverable by such inspection. Items noted above as material defects should be evaluated by appropriate licensed trades before the buyer waives contingencies.

End of Report — Bayfront Property Inspections.