Final Truth table

Sensors error detect

Input	Output
0000	0
0001	1
0010	0
0011	1
0100	0
0101	1
0110	1
0111	1
1000	0
1001	1
1010	1
1011	1
1100	1
1101	1
1110	1
1111	1