


## ON/OFF

Enable: Mate Shorting Plug to Shore Power Connector. Tighten Locking Sleeve.  
 ON/OFF: Hall Effect Power Switch in Antenna. Pass the magnet over it to power on or off. Blue LED turns on when power is on.



## Mate SubConn Connectors

1. Clean connectors with canned air.
2. Spray faces with 3M silicone spray.
3. Press straight together.  
**(Do Not Bend!)**
4. Tighten locking collar.

## Install Ortman Key

1. Press sections together.
2. Using needlenose pliers, insert the ortman cord in the access slot.
3. Push the cord into the channel.
4. Use pliers to guide it past the access slots.


## Post-Dive

### Freshwater Rinse

**Caution!** Do not power wash the AUV or its components as this may cause damage to the AUV or its components.


**Caution!** Verify dummy plugs and bleed screw are installed before rinsing the forward endcap.


1. Rinse the outside of all fairings with fresh water.
2. Wipe down surfaces with a sponge or cloth rag.
3. Starting with the tail section, rinse all component subsystems with fresh water.
4. Separate the tail section from the payload section by removing the ortman key.
5. Rinse the front endcap of the tail section. The depth sensor hole in the center of the lower half must be flushed with fresh water.



### Charge Battery

1. Connect Charging Brick to AUV's Shore Power Connector. Charging a fully depleted battery requires 4-6 hours.





AUV Quick Reference Card  
000-021-892RA ECO 3379  
Last Updated: 2017-08-11

**EXPORT CONTROLLED – EAR**

THESE ITEM(S) / TECHNICAL DATA CONTAIN INFORMATION SUBJECT TO U.S. GOVERNMENT EXPORT CONTROL IN ACCORDANCE WITH THE EXPORT ADMINISTRATION REGULATIONS (EAR), 15 CFR PARTS 730-774. EXPORT OF THIS DATA TO ANY FOREIGN COUNTRY OR DISCLOSURE OF THIS DATA TO ANY NON-US PERSON WITHOUT OBTAINING THE REQUIRED U.S. GOVERNMENT EXPORT APPROVALS MAY BE A VIOLATION OF FEDERAL LAW.