VIEW FROM THE ETCH FACE - SCALE 1:1 - DO NOT SCALE: USE THE DXF FOR ALL GEOMETRY



LASER CUTTING NOTES

1. Cut the profile and all holes from the DXF file S180-06068-47009-1.dxf (layer CUT).
2. **ETCH ALL TEXT ON LAYER ETCH (shown blue on this sheet): the part number S180-06068-47009-1 and every hole label. Do not omit any etching.**
3. Etch on the face shown - this view is from the etch side.
4. Material: MILD STEEL 6 mm thick.
5. Remove all burrs and sharp edges.

HOLE LABELS (etched next to each hole, shown blue):

R6 x1 - 6 mm reamed dowel hole - ream after cutting (laser cut Ø5.8)
M8 x1 - M8 tapped hole - drill and tap after cutting (laser cut Ø5.5)

POLAR	**LASER CUTTING INSTRUCTION**
DESCRIPTION: **RING SUPPORT - JIG**	
PART No: **S180-06068-47009**	REV: **1**
MATERIAL: **MILD STEEL**	THICKNESS: **6 mm**
QTY:	SCALE: **1:1** / SHEET: **A4**
DRAWN:	DATE: **16/10/2026** / DXF FILE: **S180-06068-47009-1.dxf**