
## 1 Conveyor breakdown





**Failed** **Conveyor**

**Injected** UR5e-1 holds the trimmed peg, before release onto the Conveyor

**At failure**
KET4_Square_4mm in UR5e-1
gear_small in UR5e-4

**Disrupted** transport to Buffer

## 2 ur5e-1 breakdown




**Failed** **UR5e-1**

**Injected** M1 has finished; UR5e-1 has approached but not grasped

**At failure** trimmed KET4_Square_4mm in M1
UR5e-1 stopped in M1's front access, gripper empty

**Disrupted** M1 unloading

## 3 Machining breakdown during part processing





**Failed** **M1**

**Injected** 18% into M1's 5 s trim job

**At failure**
KET4_Square_4mm partly trimmed in M1
RGOCG4-50_Round_4mm still trimming in M2

**Disrupted** square trimming at M1

## 4 Part slippage




**Failed** **UR5e-4**

**Injected** gear_small half lowered onto the Assembly Board

**At failure** gear_small upright in UR5e-3's region
KET4_Square_4mm held by UR5e-3

**Disrupted** gear_small placement