
Failure scenarios
1 Conveyor breakdown
2 ur5e-1 breakdown
3 Machining breakdown during part processing
4 Part slippage
Storage
KUKA KMR
M1
M2
UR5e-1
UR5e-2
Conveyor
Buffer
UR5e-3
Exit
Assembly Board
Printer
UR5e-4
Part transfer
KMR route
KMR docking pose
Conveyor loading position
Staging tray
UR5e reach (0.85 m)
KET square peg (×4)
RGOCG round peg (×4)
Printed gear (×3)
1 m