

Friday, Mar

Harvey Dhillon 3/13 7:48 PM



Anyone know if we have an ongoing issue at Haslet?

Kevin Buczek 3/13 7:49 PM



We do

[Shane Villalpando](#) can you jump on and take a look? Mitchel is on the in

Ethan Crowder 3/13 7:49 PM



I can confirm, I'm on the phone with them now about their ACB system

Site reports under zone 5, they're unable to get a pair.

Kevin Buczek 3/13 7:50 PM



Andy believes they did not keep an eye on system between sorts and now

Harvey Dhillon 3/13 7:51 PM



Yeah sounds like it from the description above

Ethan Crowder 3/13 7:55 PM

EC

What other possibilities could there be, if low charged AGV's isn't the cause?

Harvey Dhillon 3/13 7:55 PM

HD

When u say unable to get a pair, what do you mean?

Ethan Crowder 3/13 7:58 PM

EC

They verified they had earlier issues with a low battery AMR. When they attempted to replace AMRs are going to the hospital lane. So when they say pairing, it sounds like they attempted replacement AMRs

Harvey Dhillon 3/13 7:59 PM

HD

Oh, I bet they didn't remove and add properly, so it isn't getting a task correctly



The low battery isn't the cause of the current issue, it's just started the problem

Ethan Crowder 3/13 8:02 PM

EC

We've had calls prior where they didn't add an AGV correctly. However, Mitchell added it to the database. Is this the only way to correct?

Harvey Dhillon 3/13 8:03 PM

HD

No I think there is an easier way, Shane should be able to help. Maybe they

Leave it out for the rest of the sort

Kevin Buczek 3/13 8:04 PM



Shane: 805-266-2489

He doesnt have his PC with him but cant help over the phone best he can

Ethan Crowder 3/13 8:04 PM Edited

EC

Site attempted they tried adding two AGVs, one being underneath the rack

Kevin Buczek 3/13 8:16 PM



Any luck?

Darrell Halterman 3/13 8:18 PM

DH

When they remove/add you have to swing them through the hospital to re

Ethan Crowder 3/13 8:20 PM



Kevin Buczek 3/13/2026 8:16 PM
Any luck?

I'm currently waiting on verification of their CBRE workorder

Kevin Buczek 3/13 8:22 PM



If they gave us the CBRE work order number thats enough

Ethan Crowder 3/13 8:22 PM



Ok

Edited

Site reports they attempted/have removed the AGVs they tried to add

Kevin Buczek 3/13 8:28 PM



Have you connected with Shane?

Ethan Crowder 3/13 8:30 PM



Working on that, I'm still on my cell phone with site POC

Edited

Site POC and I are transferring to a teams meeting, I'm calling Shane now

Edited

Edited

Kevin Buczek 3/13/2026 8:28 PM

Have you connected with Shane?

Shane didn't answer, I left a voicemail

I have a teams meeting going on now with site POC. I can drop meeting info i

Ethan Crowder 3/13 8:48 PM



Any other points of contact I can try to engage?

Kevin Buczek 3/13 8:50 PM



It's really only Mitchel, Shane, and Andy

Christopher Corbett 3/13 8:50 PM



Ethan Crowder 3/13/2026 8:48 PM

Any other points of contact I can try to engage?

If the root of the issue is robots not properly rostered in RMS, then our only c

EC

[illegible]

Site removed robot 158 from system

Christopher Corbett 3/13 8:56 PM



Is that the issue?
Was it 158 that was under the trays, or is that something else going on?

Ethan Crowder 3/13 8:57 PM



Tony on site removed robot 158 he said. However, zone 5 is still having issues.

Darrell Halterman 3/13 8:57 PM



Are there any bots with stuck tasks?



Not moving

Christopher Corbett 3/13 9:00 PM



153 is still reporting no charging - I don't know exactly what the issues are with zone 5, it could be that 153 is still stuck in zone 5 if it's trying to go to charge but it lost its QR code

Kevin Buczek 3/13 9:09 PM



Ethan did you get ahold of Shane?

If not give me your number. Someone else called him and talked

Ethan Crowder 3/13 9:10 PM



Yes, but site believes removing robot 158 may have fixed the issue. Apparently the system has began working. I'm still on the call to monitor and make sure the system is indeed operational



Kevin Buczek 3/13 9:12 PM



That's great

Salesforce Case Data



- ✓  **Ethan Crowder** March 13, 2026 at 7:36 PM 
 Case created
Case Number: 00228723
Subject: ACB System Down
Type: Malfunction
Account Name: UPS Fort Worth, TX (Haslet)
CSC:
Status: New
Priority: 2 - High: Production seriously impacted

 Comment

- ✓  **Ethan Crowder** March 13, 2026 at 7:37 PM 
 Case status updated
Status: New to In Progress

 Comment

- ✓  **System** March 13, 2026 at 7:37 PM
 Case updated
Status: Resolved to Closed
Status: Escalated to Resolved
Status: In Progress to Escalated


[Show All Updates](#)

- ✓  **Ethan Crowder** March 13, 2026 at 7:37 PM 
 To: Internal
Currently waiting on site to issue a CBRE work order

 Comment

✓  **Ethan Crowder** March 13, 2026 at 8:30 PM 
 Case status updated
Status: In Progress to Escalated
 Comment

✓  **Ethan Crowder** March 13, 2026 at 8:45 PM 
 To: Internal



 Comment



The screenshot shows the SAP S/4HANA Fiori 'Manage Material' app. The table displays a list of materials with the following columns: Material, Material Type, Basic Unit of Measure, Basic Price, and various status indicators. The material '10000000' is highlighted in blue.

Material	Material Type	Basic Unit of Measure	Basic Price	Status
10000000	10000000	10000000	10000000	10000000
10000001	10000001	10000001	10000001	10000001
10000002	10000002	10000002	10000002	10000002
10000003	10000003	10000003	10000003	10000003
10000004	10000004	10000004	10000004	10000004
10000005	10000005	10000005	10000005	10000005
10000006	10000006	10000006	10000006	10000006
10000007	10000007	10000007	10000007	10000007
10000008	10000008	10000008	10000008	10000008
10000009	10000009	10000009	10000009	10000009
10000010	10000010	10000010	10000010	10000010

[illegible]

Tony reported that after removing robot 158, the system began functioning again. I remained on the call for approximately 10 minutes for him to continue monitoring. He reported the system remained operational and we've dropped off our teams call.



Comment



 Comment



Ethan Crowder



To: [Tony Angton](#) 

March 1

FORTNA

The following Case has been Closed:

Case: 00228723

Account: UPS Fort Worth, TX (Haslet) -

Contact Name: Tony Angton

Installation Group: IG0011744 - UPS - TXRTH - HASLET, TX

Affected Asset: Z - UPS Fort Worth, TX (Haslet)

Case Opened: 3/13/2026 7:36 PM

Case Resolved: 3/13/2026

Priority: 2 - High: Production seriously impacted

Subject: ACB System Down

Description: Site reports under zone 5, they're unable to get a pair. AMR had a low battery level under the rack. Site replaced the AMR, and every AMR goes to the hospital.

Resolution Details: Site removed robot 158, which was shown to not be mapped. After doing so, the ECB system was reported to be functional again.

Additional Comments:

Sincerely,

FORTNA Technical Support Team

View Work Order Detail - C3063262	
Work Order Location	
Country, St, City: US, TX, Fort Worth Floor: All Floors (DECR-SMC Use Only) Location within: Asbestos Present?:	Building: TXRTH - HASLET HUB Area: All Areas (DECR-SMC Use Only) Location Phone: 682-287-4300
Important Dates	
Entered: 3/13/2026 6:47:04 PM CST Next Arrival:	Response Target: 3/13/2026 8:44:00 PM CST Completed:
General Information:	
Priority: P1 - Emergency Requested By: Tony Angton Contact Name: Tony Angton Contact Phone: 682-287-4300 Problem Description: 144017 - UPS - Conveyor/Sorting Equipment - Emergency Breakdown-Mechanical:-> ACB- need amr's to pair in zone 5. Cost Center: CUP668D23 Bid Amount: Facility Manager: William Romons	Status: D - Dispatched Company Covered: Yes Est. Service Cost: 2500.00 USD Service Center: CBRE-UPS SHARED SERVICE CENTER Completion Description: Invoice: No Invoice Facility Manager Phone #: +1 (682) 443-7858
Assignment:	
Type: Vendor Number: 574281/1 Name: Material Handling Systems Inc(Mt Washing	

 Comment