CURRENTLY UNSUPPORTED PERIMETERS ARE NOT ADDRESSED.

Dashed Red Line - Represents actual Model

Unsupported Perimeters Don't
EVER print correctly!

PROPOSAL TO DEAL WITH UNSUPPORTED PERIMETERS.

OR B) Extended SOLID Infill
As is done now (extended bridge region)

A) Internal Anchor Perimeter
To Sandwich BRIDGED Membrane?

Membrane Supports
Perimeters

Optionally, vertical support walls
offset 1 "perimeter" width from perimeter"

Automatic Membrane under Unsupported Perimeters