Repairer

ONEHUNGA PANEL & PAINT -

Phone , Fax , Email info@onehungapp.co.nz

ESTIMATE ASSESS Vero Insurance NZ Ltd				
Owner	Arrco Sterling Mota			
Vehicle	2016-BMW X5			
Reg No Claim #	KNZ151 N008840864			
Our Ref	3084303			
Quote No	41363			
Assessor	Warren Paton			
RR: (\$85.00 ► \$80.00)		Hrs		Adj
1. Front B/Bar euro (All Hardware)		1.25	•	4.25
2. top rad cover		0.30	•	0.20
3. LH & RH kidney grill	les	0.40	•	0.00
4. LH & RH FB spotlian	nps & housings	0.40	>	0.00
5. squirters & hoses		0.50	•	0.00
6. sensors & wiring		0.50	•	0.00
7. tow eye cover		0.10	•	0.00
8. middle grille		0.30	>	0.00
9. lower grille		0.40	>	0.00
10. LH bezel		0.20	•	0.00
11. RH bezel		0.20	•	0.00
12. R/H/F Guard wheel a	arch mold	0.50	>	
13. L/H/F Guard wheel a	arch mold	0.50	•	
14. L/H/F Guard badge &	& reback	0.20	>	
15. L/H Headlamp (not r	required)	0.35	>	0.00
	—— SubTotal Hrs	6.10		5.65
	SubTotal \$	\$518.50	•	\$452.00
Repair: (\$85.00 ► \$80.00)		Hrs		Adj
16. beamset (not required)		0.50	•	0.00
17. Front B/Bar (minima		2.00		1.25
18. L/H/F Guard wheel a		0.40	•	0.25
	—— SubTotal Hrs	2.90		1.50
	SubTotal \$	\$246.50		\$120.00
Daint: (\$200)	SubTotal φ	φ240.50 Hrs	•	
Paint: (\$200) 19. Front B/Bar XL 3lay	er pearl (with caps)	1.78	•	Adj 2.00
20. L/H/F Guard wheel a		0.83	>	0.75
21. L/H/F Guard (blend)		0.50		
22. 2x squirter caps (incl	uded)	0.28	•	0.00
23. toy eye cover (includ	led)	0.18	•	0.00
24. sensors (not required		0.33	>	0.00
25. MIX & MATCH NC (Added by assessor)	OTED POOR PREVIOUS PAINT WORK	0.00		
26. Variance (@\$-5)		0.00	•	0.00

SubTotal Hrs	3.90	3.25
SubTotal \$	\$775.00	\$650.00
- Total Labour Hrs	12.90	▶ 10.40
Total Labour	\$1,540.00	\$1,222.00
Part: 27. LF ALLOY (Added by assessor)	\$ \$0.00	Adj ▶ \$0.00
28. LR ALLOY (Added by assessor)	\$0.00	\$0.00
29. parts as per pt 7713727 - Used	\$1,350.00	, , , , , ,
30. success fee - Used	\$48.83	
31. MU @ 15% - Used (SEND THE PARTS TRADER PARTS LIST PLEASE)	\$202.50	\$0.00
32. FREIGHT (Added by assessor)	\$0.00	\$45.00
- SubTotal \$	\$1,601.33	▶ \$1,443.83
Sublet:	\$	Adj
33. WHEEL ALIGNMENT REPORT (Added by assessor)	\$0.00	\$110.00
34. 2 TYRES NON RUNFLAT AS FITTED NEED TREAD REPORT & QUOTE APPROX (Added by assessor)	\$0.00	\$600.00
35. ELECTRICAL SCAN (Added by assessor)	\$0.00	\$90.00
- SubTotal \$	\$0.00	▶ \$800.00
Other:	\$	Adj
36. freight	\$45.00	\$0.00
37. materials	\$38.25	
38. WHITE PLASTIC RIVETS APPROX (Added by assessor)	\$0.00	\$25.00
39. customer stated air suspension damage, inspection & repair @ invoice +10% EST (NEED TO SEE ALL CLIENTS INVOICES)	\$1,141.25	\$ 0.00
40. waste fee (INCLUDED)	\$8.00	\$0.00
41. tyres & wheel alignment @ invoice +10%	\$1.00	
SubTotal \$	\$1,233.50	\$64.25
Total	\$4,374.83	\$3,530.08
GST	\$656.22	\$529.51
Grand Total	\$5,031.05	\$4,059.59

Assessor's comment

Hi Ant

I have been awaiting your call as per the message left with Luke when I called in last week. Please have the client supply all invoices for parts they may have replaced please before the mechanical is consider as part of the claim. Quote for the Tyres along with remaining tread report.

Once you have these please call. Ph 021 644 011 Images & Invoices please.

Regards

Warren Paton Assessor

Warren Paton, 021 644 011, info@waynejones.co.nz, Auckland, NZ