



Fig. 18 Drift mobility of Ge, Si, and GaAs at 300 K versus impurity concentration. (After Casey and Panish, Ref. 9; Prince, Ref. 36; Beadle, Plummer, and Tsai, Ref. 38.)