


## Team 5 meeting with Andrew



	When relay turns on it shorts
	When relay torns on it
W y	12v - 5v
	should take 12' Nopin to
	- Stepper motor psu pin
	840401
- 18	Clean up erc errors twarnings
	CICALI DE LA CONTRACTOR
41 E	Use pin head mode library
and the second of	to connected
1,415	
28114	+ Genearal feed back Flooded
	- ground planes
12.	
	+ Need thicker traces
	Power traces must be
	08 50 mils or 100 mils
	Copulling 12 of the second
5 ,, 1	t crystal needs to be much closer to at mega
	to at mega
	The street of th
110	+ 100 n F1 cap that bipasses needs
	C4
	to be right next to the
	Chip

