| annual_failure_rate | model | | | |
|---------------------|-------------------------|--|--|--|
| 3.85 | HGST HMS5C4040ALE640 | | | |
| 0.99 | Hitachi HDS5C3030ALA630 | | | |
| 1.65 | Hitachi HDS5C4040ALE630 | | | |
| 1.03 | Hitachi HDS722020ALA330 | | | |
| 1.01 | Hitachi HDS723030ALA640 | | | |
| 129.88 | ST1500DL003 | | | |
| 10.35 | ST3000DM001 | | | |
| 23.29 | ST31500341AS | | | |
| 10.52 | ST31500541AS | | | |
| 7.90 | ST32000542AS | | | |
| 6.91 | ST33000651AS | | | |
| 4.17 | ST4000DM000 | | | |
| 1.12 | ST4000DX000 | | | |
| 6.93 | TOSHIBA DT01ACA300 | | | |
| 3.79 | WDC WD30EFRX | | | |
| 6.32 | WDC WD30EZRX | | | |
| 219.71 | | | | |

| model | annual_failure_rate | drive_days | failures |
|-------------------------|---------------------|------------|----------|
| HGST HMS5C4040ALE640 | 3.85 | 9481 | 1 |
| Hitachi HDS5C3030ALA630 | 0.99 | 962450 | 26 |
| Hitachi HDS5C4040ALE630 | 1.65 | 508293 | 23 |
| Hitachi HDS722020ALA330 | 1.03 | 993166 | 28 |
| Hitachi HDS723030ALA640 | 1.01 | 216033 | 6 |
| ST1500DL003 | 129.88 | 14333 | 51 |
| ST3000DM001 | 10.35 | 938495 | 266 |
| ST31500341AS | 23.29 | 142602 | 91 |
| ST31500541AS | 10.52 | 426693 | 123 |
| ST32000542AS | 7.90 | 64670 | 14 |
| ST33000651AS | 6.91 | 63356 | 12 |
| ST4000DM000 | 4.17 | 419819 | 48 |
| ST4000DX000 | 1.12 | 32726 | 1 |
| TOSHIBA DT01ACA300 | 6.93 | 10534 | 2 |
| WDC WD30EFRX | 3.79 | 38534 | 4 |
| WDC WD30EZRX | 6.32 | 98204 | 17 |
| Total | 219.71 | 4939389 | 713 |